

#### UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I 2100 RENAISSANCE BOULEVARD, SUITE 100 KING OF PRUSSIA, PENNSYLVANIA 19406-2713

December 10, 2019

Mr. Bryan C. Hanson Senior Vice President, Exelon Generation Company, LLC President and Chief Nuclear Officer, Exelon Nuclear Exelon Generation Company, LLC 4300 Winfield Road Warrenville, IL 60555

### SUBJECT: JAMES A. FITZPATRICK NUCLEAR POWER PLANT – TEMPORARY INSTRUCTION 2515/193 INSPECTION REPORT 05000333/2019013

Dear Mr. Hanson:

On November 7, 2019, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at James A. FitzPatrick Nuclear Power Plant and discussed the results of this inspection with Mr. Chris Adner, Operations Director, and other members of your staff. The results of this inspection are documented in the enclosed report.

No findings or violations of more than minor significance were identified during this inspection.

This letter, its enclosure, and your response (if any) will be made available for public inspection and copying at <u>http://www.nrc.gov/reading-rm/adams.html</u> and at the NRC Public Document Room in accordance with Title 10 of the *Code of Federal Regulations* 2.390, "Public Inspections, Exemptions, Requests for Withholding."

Sincerely,

### /**RA**/

Marc S. Ferdas, Team Leader Technical Support and Administrative Team Division of Reactor Projects

Docket No. 05000333 License No. DPR-59

Enclosure: As stated

cc w/ encl: Distribution via LISTSERV®

#### SUBJECT: JAMES A. FITZPATRICK NUCLEAR POWER PLANT – TEMPORARY INSTRUCTION 2515/193 INSPECTION REPORT 05000333/2019013 DATED DECEMBER 10, 2019

DISTRIBUTION:

| DLew, RA             | (R10RAMAIL RESOURCE) |
|----------------------|----------------------|
| RLorson, DRA         | (R10RAMAIL RESOURCE) |
| DCollins, DRP        | (R1DRPMAIL RESOURCE) |
| BWelling, DRP        | (R1DRPMAIL RESOURCE) |
| JYerokun, DRS        | (R1DRSMAIL RESOURCE) |
| PKrohn, DRS          | (R1DRSMAIL RESOURCE) |
| MFerdas, DRP         |                      |
| ECarfang, DRP        |                      |
| CLally, DRP          |                      |
| SObadina, DRP        |                      |
| EMiller, DRP, SRI    |                      |
| ATrudell, DRP, AA    |                      |
| JQuichocho, RI OEDO  | 0                    |
| RidsNrrPMFitzPatrick | Resource             |
| RidsNrrDorlLpl1 Resc | ource                |
| ROPReports Resource  | e                    |

#### DOCUMENT NAME: G:\DRP\BRANCH1\FitzPatrick\REPORTS\Fitz TI -193 2019013.docx ADAMS ACCESSION NUMBER: ML19345D572

| SUNSI Review | SUNSI Review Non-Sensitive   Sensitive Sensitive |  | <ul><li>Publicly Available</li><li>Non-Publicly Available</li></ul> |  |
|--------------|--|--|---|--|
| OFFICE       | RI/DRP   |  |   |  |
| NAME         | MFerdas  |  |   |  |
| DATE         | 12/10/19   |  |   |  |

OFFICIAL RECORD COPY

# U.S. NUCLEAR REGULATORY COMMISSION Inspection Report

| Docket Number:         | 05000333   |
|------------------------|--|
| License Number:        | DPR-59   |
| Report Number:         | 05000333/2019013   |
| Enterprise Identifier: | I-2019-013-0019  |
| Licensee:              | Exelon Generation Company, LLC   |
| Facility:              | James A. FitzPatrick Nuclear Power Plant   |
| Location:              | Oswego, NY   |
| Inspection Dates:      | November 4, 2019 to November 8, 2019   |
| Inspectors:            | F. Arner, Senior Reactor Analyst<br>T. Daun, Resident Inspector  |
| Approved By:           | Marc S. Ferdas, Team Leader<br>Technical Support and Administrative Team<br>Division of Reactor Projects |

#### SUMMARY

The U.S. Nuclear Regulatory Commission (NRC) continued monitoring the licensee's performance by conducting a Temporary Instruction 2515/193 inspection at James A. FitzPatrick Nuclear Power Plant, in accordance with the Reactor Oversight Process. The Reactor Oversight Process is the NRC's program for overseeing the safe operation of commercial nuclear power reactors. Refer to <a href="https://www.nrc.gov/reactors/operating/oversight.html">https://www.nrc.gov/reactors/operating/oversight.html</a> for more information.

### **List of Findings and Violations**

No findings or violations of more than minor significance were identified.

# **Additional Tracking Items**

None.

### **INSPECTION SCOPES**

Inspections were conducted using the appropriate portions of the inspection procedures (IPs) in effect at the beginning of the inspection unless otherwise noted. Currently approved IPs with their attached revision histories are located on the public website at <a href="http://www.nrc.gov/reading-rm/doc-collections/insp-manual/inspection-procedure/index.html">http://www.nrc.gov/reading-rm/doc-collections/insp-manual/inspection-procedure/index.html</a>. Samples were declared complete when the IP requirements most appropriate to the inspection activity were met consistent with Inspection Manual Chapter (IMC) 2515, "Light-Water Reactor Inspection Program - Operations Phase." The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel to assess licensee performance and compliance with Commission rules and regulations, license conditions, site procedures, and standards.

# **OTHER ACTIVITIES – TEMPORARY INSTRUCTIONS, INFREQUENT AND ABNORMAL**

<u>2515/193 - Inspection of the Implementation of EA-13-109: Order Modifying Licenses with</u> <u>Regard to Reliable Hardened Containment Vents Capable of Operation under Severe Accident</u> <u>Conditions</u>

Inspection of the Implementation of EA-13-109: Order Modifying Licenses with Regard to Reliable Hardened Containment Vents Capable of Operation under Severe Accident Conditions (1 Sample)

(1) Based on samples selected for review, the inspectors verified that Exelon implemented appropriate elements of the reliable hardened containment wetwell vent as described in the plant specific submittal and the associated safety evaluation (ADAMS Accession No. ML18360A635) and NRC Order EA-13-109 Phase 1, "Reliable, Severe Accident Capable Wetwell Venting System" (ADAMS Accession No. ML13143A321).

The inspectors verified that Exelon:

- installed the hardened containment vent system (HCVS) to meet the performance objectives outlined in Section A.1.1 of Attachment 2 to the Order EA-13-109;
- installed the HCVS system with the design features specified in Section A.1.2 of Attachment 2 to the Order EA-13-109;
- designed the HCVS to meet the quality standards described in Section A.2 of Attachment 2 to the Order EA-13-109;
- developed and implemented adequate maintenance and testing of HCVS equipment to ensure their availability and capability;
- developed and issued procedures to safely operate the HCVS using normal power supplies, during extended loss of alternating current power (ELAP), and a postulated severe accident scenario, and integrated the procedures into existing plant procedures; and
- trained their staff to assure personnel can proficiently operate the HCVS.

Based on samples selected for review, the inspectors verified that Exelon implemented appropriate elements of the reliable wetwell venting strategy as described in the plant specific submittal and the associated safety evaluation (ADAMS Accession No. ML18360A635) and NRC Order EA-13-109 Phase 2,

"Reliable, Severe Accident Capable Drywell (or alternative strategy) Venting System" (ADAMS Accession No. ML13143A321).

The inspectors verified that Exelon:

- developed a strategy making it unlikely that Exelon would need to vent from the containment drywell;
- implemented the severe accident water addition (SAWA)/severe accident water management (SAWM) systems as defined and fulfilled functional requirements for installed and portable equipment;
- installed and/or identified the previously installed instrumentation necessary to implement SAWM;
- developed and implemented adequate maintenance and testing of SAWA/SAWM equipment to ensure availability and capability;
- developed and issued procedures to safely operate the SAWA/SAWM during an ELAP and during postulated severe accident scenario, and integrated their procedures into their existing plant procedures such that entry into and exiting from the procedures are clear when using existing plant procedures; and
- trained their staff to assure personnel can proficiently operate the HCVS during an ELAP and accident scenario.

The inspectors verified that any noncompliance with requirements, and standards identified during the inspection, were entered into Exelon's corrective action program.

# **INSPECTION RESULTS**

No findings were identified.

# EXIT MEETINGS AND DEBRIEFS

The inspectors verified no proprietary information was retained or documented in this report.

• On November 7, 2019, the inspectors presented the Temporary Instruction 2515/193 inspection results to Mr. Chris Adner, Operations Director, and other members of the licensee staff.

# **DOCUMENTS REVIEWED**

| Inspection<br>Procedure | Туре                         | Designation                                      | Description or Title   | Revision or Date |
|-------------------------|------------------------------|--|--|------------------|
| 2515/193 Calculations   | Calculations                 | JAF-CALC-15-<br>00013                            | Hardened Containment Vent System: N2 Bottle and Venting Capacity | 0                |
|                         | JAF-CALC-15-<br>00031        | FLEX Strategy – Portable Generator System Sizing | 0  |                  |
|                         |                              | JAF-CALC-17-<br>00104                            | HCVS Phase 2 SAWA Hydraulic Analysis                             | 0                |
|                         | Corrective Action            | 04220576   |  |                  |
|                         | Documents                    | 04288408   |  |                  |
|                         |                              | 3992547  |  |                  |
|                         |                              | 4084456  |  |                  |
|                         |                              | 4084578  |  |                  |
|                         |                              | 4088244  |  |                  |
|                         |                              | 4091301  |  |                  |
|                         |                              | 4091760  |  |                  |
|                         |                              | 4091828  |  |                  |
|                         |                              | 4109111  |  |                  |
|                         |                              | 4120276  |  |                  |
|                         |                              | 4126448  |  |                  |
|                         |                              | 4159500  |  |                  |
|                         |                              | CR-JAF-2017-                                     |  |                  |
|                         |                              | 01155  |  |                  |
|                         | Corrective Action            | 04295041   |  |                  |
|                         | Documents                    | 04295115   |  |                  |
| Ins                     | Resulting from<br>Inspection | 4295114  |  |                  |
|                         | Drawings                     | FB-48A   | Flow Diagram Fire Protection Water Piping System 76              | 34               |
|                         | -                            | FB-48B   | Site Utilities Fire Protection Water Supply Flow Diagram         | 11               |
|                         |                              | FM-18B   | Flow Diagram Drywell Inerting CAD                                | 45               |
|                         |                              | FM-20A   | Flow Diagram Residual Heat Removal System 10                     | 72               |
|                         |                              | FM-20B   | Flow Diagram Residual Heat Removal System 10                     | 72               |
|                         |                              | FM-39C   | Flow Diagram Instrument Air Reactor Building and Drywell         | 33               |

| Inspection<br>Procedure | Туре        | Designation   | Description or Title   | Revision or<br>Date |
|-------------------------|-------------|---|--|---------------------|
|                         |             |   | System 39  |                     |
|                         |             | SK-EC620605-01  | Process Flow Diagram Severe Accident Water Addition (SAWA) Severe Accident | 0                   |
|                         |             |   | Water Management (SAWM)  |                     |
|                         | Procedures  | AOP-49  | Station Blackout   | 25                  |
|                         |             | CC-JF-118-1004  | HVCS Final Integrated Plan   | 0                   |
|                         |             | CC-JF-118-101   | Beyond Design Basis Administrative Controls                                | 2                   |
|                         |             | EOP-2   | RPV Control  | 11                  |
|                         |             | ESP-37.002  | HCVS Manual Valve Panel Valve Testing                                      | 0                   |
|                         |             | FSG-001   | Initial Assessment and FLEX Equipment Staging                              | 6                   |
|                         |             | FSG-003   | Alternate Reactor Vessel Cooling   | 6                   |
|                         |             | FSG-004   | Alternate Containment Cooling  | 2                   |
|                         | FSG-101     | Beyond Design Basis External Events EP Communications | 4  |                     |
|                         |             | FSG-ELAP  | Extended Loss of AC Power (ELAP)   | 6                   |
|                         |             | SAOG-1  | RPV and Primary Containment Injection                                      | 0                   |
|                         |             | SAOG-2  | RPV, Containment, and Radioactivity Release Control                        | 4                   |
|                         |             | SPEC-15-00001   | Hardened Containment Vent System: Instrumentation and Batteries            | 0                   |
|                         |             | ST-76AD   | East Diesel Fire Pump 76 P-4 Performance Test                              | 2-15-19             |
|                         | Work Orders | 336844  |  |                     |
|                         |             | 374741  |  |                     |
|                         |             | 4666902   |  |                     |
|                         |             | 4935135   |  |                     |
|                         |             | 52336966  |  |                     |
|                         |             | 82619359  |  |                     |