NRC INSPECTION MANUAL

IIPB

Change Notice 01-020

DELETED: TRANSMITTED:

<u>Number</u> <u>Date</u> <u>Number</u> <u>Date</u>

1. IMC 2620 02/11/93 IMC 2620 10/05/01

TRAINING: No special training requirements have been identified for any documents

issued with this change notice.

REMARKS: IMC 2620 (On-Site Construction Reviews of Remedial Action at Inactive

Uranium Mill Tailing Sites (Title I, Uranium Mill Tailing Radiation Control Act)) has been reviewed and revised. Changes were in section 04.02 where the Division of Low-Level Waste Management was changed to Division of Fuel Cycle Safety and Safeguards. Section 04.03 was deleted because the Uranium Recovery Field Office no longer exists. Ownership of this document is now assigned to the, Fuel Cycle Licensing Branch, Division of Fuel Cycle

Safety and Safeguards, NMSS.

DISTRIBUTION: Standard

END

Issue Date: 10/05/01 - 1 - 01-020