



U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

DCS-NRC-000378  
13 November 2014


Subject: Docket Number 070-03098  
Shaw AREVA MOX Services  
Mixed Oxide Fuel Fabrication Facility  
Closure of Interim Report Notification: Deformed Bar Anchors

Reference: 1. Letter from K. Trice to U.S. NRC Document Control Desk, DCS-NRC-000374,  
"Part 21 60-Day Interim Report Notification: Nelson Deformed Bars," dated  
May 28, 2014  
2. Letter from K. Trice to U.S. NRC Document Control Desk, DCS-NRC-000376,  
"Updated Interim Report Notification: Nelson Deformed Bars," dated  
August 26, 2014

CB&I AREVA MOX Services, LLC (MOX Services), submitted an interim report (Reference 1) and an updated interim report (Reference 2) regarding Nelson Deformed Bars. Evaluation of the condition identified in the interim reports has been completed. This condition has been determined to not be reportable in accordance with 10 CFR Part 21.

If you have any questions, please feel free to contact me at (803) 442-6485 or Dealis Gwyn, Licensing Manager at (803) 819-2780.

Sincerely,



David Del Vecchio, President

Document Control Desk  
U.S. Nuclear Regulatory Commission  
DCS-NRC-000378  
13 November 2014  
Page 2 of 2

cc :

Scott Cannon, NNSA/SRS  
Mosi Dayani, NNSA/SRS  
William Gloersen, USNRC/RII  
Mark Gober, MOX Services  
Dealis Gwyn, MOX Services  
Chad Huffman, USNRC/SRS  
Kevin Morrissey, USNRC/HQ  
Gilles Rousseau, MOX Services  
Deborah Seymour, USNRC/RII  
Donald Silverman, ML&B  
David Tiktinsky, USNRC/HQ  
Rodney Whitley, MOX Services  
Paul Whittingham, MOX Services  
Bryan Wilkes, MOX Services  
Lauren Wylie, MOX Services  
EDMS: Corresp\\Outgoing\NRC\2014 NRC