

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 37

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 37

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Management and Supervision / IR			
32 - Supervision / command and control LTA	H - Health Physics	H - Health Physics	050-00348/2003-005
32 - Supervision / command and control LTA	H - Health Physics	H - Health Physics	050-00348/2003-005
40 - Individual Corrective Action LTA	G - Engineering	M - Maint / Repair	050-00348/2004-003
40 - Individual Corrective Action LTA	G - Engineering	M - Maint / Repair	050-00348/2004-003
41 - Action not begun or untimely	G - Engineering	M - Maint / Repair	050-00348/2004-009
44 - Corrective Action program LTA	G - Engineering	M - Maint / Repair	050-00348/2004-003
47 - Root Cause LTA	G - Engineering	M - Maint / Repair	050-00348/2004-003
Number of Items for this Docket: 7			
Percent of Total for this Docket: 19			
Procedures and Reference Document / IR			
12 - Procedure technical content LTA	G - Engineering	G - Design	050-00348/2004-004
12 - Procedure technical content LTA	G - Engineering	G - Design	050-00348/2004-004
12 - Procedure technical content LTA	G - Engineering	G - Design	050-00348/2004-007
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00348/2004-002
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00348/2004-004
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00348/2004-009
13 - Procedure has human factors deficiencies	G - Engineering	G - Design	050-00348/2004-004
13 - Procedure has human factors deficiencies	P - Procedure Writers	P - Procedure Dev	050-00348/2004-009
Number of Items for this Docket: 8			
Percent of Total for this Docket: 22			
Training / IR			
02 - Training LTA	O - Operations	O - Control Room Ops	050-00348/2004-004
02 - Training LTA	O - Operations	O - Control Room Ops	050-00348/2004-004
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
Work Factors / IR			
83 - Work practice or craft skill LTA	G - Engineering	M - Maint / Repair	050-00348/2004-006
83 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00348/2004-004
83 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00348/2004-004
83 - Work practice or craft skill LTA	O - Operations	Q - Fire Protection	050-00348/2004-004
83 - Work practice or craft skill LTA	Z - Other	M - Maint / Repair	050-00348/2004-004
84 - Non-conserv. decision / Questioning LTA	G - Engineering	M - Maint / Repair	050-00348/2004-002

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 37

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 37

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Work Factors / IR			
84 - Non-conserv. decision / Questioning LTA	H - Health Physics	H - Health Physics	050-00348/2003-005
93 - Awareness or attention LTA	G - Engineering	F - Modification	050-00348/2004-004
93 - Awareness or attention LTA	G - Engineering	F - Modification	050-00348/2004-004
93 - Awareness or attention LTA	G - Engineering	G - Design	050-00348/2004-007
93 - Awareness or attention LTA	M - Mechanical	H - Health Physics	050-00348/2003-005
94 - Log-keeping or review LTA	O - Operations	A - Administrative	050-00348/2004-004
94 - Log-keeping or review LTA	O - Operations	A - Administrative	050-00348/2004-004
Number of Items for this Docket: 13			
Percent of Total for this Docket: 35			
Management and Supervision / LER			
36 - Scheduling and planning LTA	E - Electrical	T - Testing	050-00348/2004-002-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
Procedures and Reference Document / LER			
12 - Procedure technical content LTA	E - Electrical	T - Testing	050-00348/2004-002-00
12 - Procedure technical content LTA	E - Electrical	T - Testing	050-00348/2004-002-00
13 - Procedure has human factors deficiencies	O - Operations	O - Control Room Ops	050-00348/2004-001-00
Number of Items for this Docket: 3			
Percent of Total for this Docket: 8			
Work Factors / LER			
84 - Non-conserv. decision / Questioning LTA	O - Operations	O - Control Room Ops	050-00348/2004-002-00
86 - Work untimely	O - Operations	O - Control Room Ops	050-00348/2004-001-00
93 - Awareness or attention LTA	O - Operations	O - Control Room Ops	050-00348/2004-002-00
Number of Items for this Docket: 3			
Percent of Total for this Docket: 8			
Total Items for this Docket: 37			
