

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 19

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 19

Facility Name: Saint Lucie 1 Docket (050- 00335)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	E - Electrical	F - Modification	050-00335/2009-006
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00335/2009-006
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00335/2009-006
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00335/2009-006
113 - Procedure / reference document development and maintenance L	E - Electrical	F - Modification	050-00335/2009-006
113 - Procedure / reference document development and maintenance L	G - Engineering	G - Design	050-00335/2009-006
Number of Items for this Docket: 6			
Percent of Total for this Docket: 32			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00335/2009-006
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00335/2009-006
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00335/2009-006
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00335/2009-006
146 - Evaluation LTA	M - Mechanical	V - Troubleshooting	050-00335/2009-006
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00335/2010-007
Number of Items for this Docket: 6			
Percent of Total for this Docket: 32			
Work Planning & Practices / IR			
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00335/2009-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00335/2009-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00335/2009-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00335/2009-006
187 - Action implementation LTA	O - Operations	O - Control Room Ops	050-00335/2009-006
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00335/2009-006
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00335/2009-006
Number of Items for this Docket: 7			
Percent of Total for this Docket: 37			
Total Items for this Docket: 19			
