

May 12, 2023

L-2023-061 10 CFR 50.36b

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Re: Turkey Point Nuclear Plant, Units 3 and 4 Docket Nos. 50-250 and 50-251

2022 Annual Radiological Environmental Operating Report

Enclosed is the 2022 Annual Radiological Environmental Operating Report for Turkey Point Units 3 and 4, as required by Technical Specification 6.9.1.3.

If you have any questions regarding this submittal, please contact Kenneth Mack at 561-904-3635.

Sincerely,

Dianne Strand General Manager, Regulatory Affairs Florida Power & Light Company

Enclosure: Annual Radiological Environmental Operating Report (2022)

cc: USNRC Regional Administrator, Region II USNRC Project Manager, St. Lucie Nuclear Plant USNRC Resident Inspector, St. Lucie Nuclear Plant



Page 1 of 56

YEAR: 2022

Docket NOS Number: 50-250, 50-251

Annual Radiological Environmental Operating Report

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 2 of 56

Annual Radiological Environmental Operating Report

TABLE OF CONTENTS

1.0	EXECUTIVE SUMMARY	5
	1.1 Radiological Environmental Monitoring Program	5
	1.2 Reporting Levels	6
	1.3 Sample Deviations	6
	1.4 Program Modifications	6
2.0		7
	2.1 Radiological Environmental Monitoring Program	7
	A. Purpose	7
	2.2 Pathways Monitored	8
	2.3 Land Use Census	8
3.0	RADIOLOGICAL ENVIRONMENTAL SAMPLING PROGRAM REQUIREMENTS	9
4.0	INTERPRETATION AND TRENDS OF RESULTS	16
	4.1 Air Particulate and Radioiodine Sample Results	16
	4.2 Thermoluminescent Dosimetry (TLD) Sample Results	17
	4.3 Waterborne Sample Results	17
	4.3.1 Surface Water Results	17
	4.3.2 Shoreline Sediment Sample Results	18
	4.4 Ingestion Sample Results	18
	4.4.1 Crustacea and Fish Sample Results	18
	4.4.2 Broad Leaf Vegetation Sample Results	18
	4.5 Land Use Census Results	18
	4.6 Interlaboratory Comparison Results	25
5.0	RADIOLOGICAL ENVIRONMENTAL MONITORING PROGRAM SUMMARY	25

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 3 of 56Annual Radiological Environmental Operating Report

ATTACHMENTS

Attachment 1 - Sample Deviations	29
Attachment 2 - Monitoring Results Tables	31
Attachment 3 - Interlaboratory Comparison Program Results	48
1.0 Summary	48
Attachment 4 - Industry Initiative Ground Water Protection Program, 2022	51
1.0 Description of Program	51
2.0 Discussion	51
3.0 Results.	51
Attachment 5 - ERRATA Data 2022	55
1.0 List of changes from the 2021 AREOR	55
TABLES	
Table 1: Exposure Pathway - Airborne	9
Table 2: Exposure Pathway - Direct Radiation	10
Table 3: Exposure Pathway - Waterborne	12
Table 4: Exposure Pathway - Ingestion	13
Table 5: Land Use Census - 2022 Nearest Residence, Garden and Milk Animal Within 5 Miles	19
Table 6: Radiological Environmental Monitoring Program Summary	26
Table 7: Sample Deviations Table	29
Table 8: Air Particulate - Gross Beta	32
Table 9: Air Particulate Composite - Gamma	33
Table 10: Air Cartridges - Iodine-131	34
Table 11: Direct Radiation - Indicators	35
Table 12: Direct Radiation- Control	35
Table 13: Surface Water - Tritium and Gamma	36
Table 14: Shoreline Sediment - Gamma	37
Table 15: Crustacea - Gamma	38

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 4 of 56Annual Radiological Environmental Operating Report

TABLES (CONT'D)

	Table 16: Fish - Gamma	39
	Table 17: Broad Leaf Vegetation - Gamma	40
	Table 18: Supplemental Direct Radiation - Indicators	41
	Table 19: Supplemental Air Particulate - Gross Beta	42
	Table 20: Supplemental Air Particulate Composite - Gamma	43
	Table 21: Supplemental Air Cartridges - Iodine-131	44
	Table 22: Supplemental Surface Water - Tritium and Gamma	45
	Table 23: Supplemental Shoreline Sediment - Gamma	46
	Table 24: Supplemental Food Crops - Gamma	47
	Table 25: DOE's Mixed Analyte Performance Evaluation Program (MAPEP) 46 results	49
	Table 26: DOE's Mixed Analyte Performance Evaluation Program (MAPEP) 47 results	50
	Table 27: Ground Water - Tritium	52
<u>FIGUF</u>	RES	
	Figure 1: Sample Collection Sites - Near Station	14
	Figure 2: Sample Collection Sites - Distant from Station	15
	Figure 3: Turkey Point 2022 REMP Gross Beta in Air, pCi/m ³	16
	Figure 4: 2022 PTN Direct Exposure TLDs: Quarterly Collection	17
	Figure 5: Onsite Tritium Monitoring Wells	54

1.0 EXECUTIVE SUMMARY

1.1 Radiological Environmental Monitoring Program

The data obtained through the Turkey Point Radiological Environmental Monitoring Program (REMP) verifies that the levels of radiation and concentrations of radioactive materials in environmental samples are not increasing. These measurements verify that the dose or dose commitment to members of the public, due to operation of Turkey Point Units 3 & 4, during the surveillance year, is well within the limits established by 10 CFR 50, Appendix I. The sampling period was from January 1, 2022 to December 31, 2022. Additionally, supplemental samples collected by the State of Florida, Department of Health (DOH), do not indicate adverse trends in the radiological environment.

All required lower limit of detection (LLD) capabilities were achieved in all sample analyses during 2022, as required by the Turkey Point Units 3 & 4 Technical Specifications. No measurable levels of radiation above baseline levels attributable to Turkey Point Nuclear operation were detected in the vicinity of PTN. The 2022 Radiological Environmental Monitoring Program thus substantiated the adequacy of source control and effluent monitoring at Turkey Point Nuclear with no observed impact of plant operations on the environment.

Turkey Point Nuclear established the REMP prior to the station's becoming operational to provide data on background radiation and radioactivity normally present in the area. PTN has continued to monitor the environment by sampling air, water, sediment, crustacea, fish and broadleaf vegetation, as well as measuring direct radiation. PTN also samples milk if milk-producing animals used for human consumption are present within five miles (8 km) of the plant.

The REMP includes sampling indicator and control locations within an approximate 20-mile radius of the plant. The REMP utilizes indicator locations near the site to show any increases or buildup of radioactivity that might occur due to station operation and control locations farther away from the site to indicate the presence of only naturally occurring radioactivity. PTN personnel compare indicator results with control results to assess any impact PTN operation might have had on the surrounding environment.

In 2022, environmental samples were collected for radiological analysis. The results of indicator locations were compared with control locations. It was concluded that no significant relationship exists between PTN operation and effect on the area around the plant. The review of 2022 data showed radioactivity levels in the environment were undetectable in many locations and near background levels in significant pathways.

Radiological environmental monitoring for the Turkey Point Plant is conducted by the State of Florida, DOH. Samples are collected and analyzed by DOH personnel. Samples are analyzed at the DOH Environmental Radiation Control Laboratory in Orlando, Florida. The 2022 Radiological Surveillance Quarterly Report data is provided by the State of Florida Bureau of Radiation Control and is presented in Attachment 2. The State of Florida is not involved in the (Industry Initiative) ground water monitoring program.

1.2 <u>Reporting Levels</u>

No samples equaled or exceeded reporting levels.

1.3 <u>Sample Deviations</u>

During 2022, environmental sampling was performed for seven media types addressed in the ODCM and for direct radiation. A total of 770 samples of the 802 scheduled were obtained. Of the scheduled samples, 96 percent were collected and analyzed in accordance with the requirements specified in the ODCM. Attachment 1 contains the listing of sample deviations and actions taken.

1.4 Program Modifications

• There were no program modifications during the reporting period.

2.0 INTRODUCTION

This report is submitted pursuant to Specification 6.9 of Turkey Point Units 3 & 4 Technical Specifications. The Annual Radiological Environmental Operating Report provides information, summaries and analytical results pertaining to the Radiological Environmental Monitoring Program for the calendar year indicated. This report covers surveillance activities described in the Offsite Dose Calculation Manual (ODCM) meeting the requirements of Unit 3 and Unit 4 Technical Specifications.

2.1 Radiological Environmental Monitoring Program

The Radiological Environmental Monitoring Program for the Turkey Point Plant is conducted pursuant to Control 5.1 of Turkey Point Unit 3 & 4 ODCM.

A. <u>Purpose</u>

The purpose of the Radiological Environmental Monitoring Program is to provide representative measurements of radiation and of radioactive materials in those exposure pathways and for those radionuclides which lead to the highest potential radiation exposures of members of the public resulting from station operation. The Radiological Environmental Monitoring Program also supplements the radiological effluent monitoring program by verifying that the measurable concentrations of radioactive materials and levels of radiation are not higher than expected on the basis of the effluent measurements and the modeling of the environmental exposure pathways.

Sample Locations, Types and Frequencies:

- Direct radiation gamma exposure rate is monitored continuously at 23 locations by thermoluminescent dosimeters (TLDs). TLDs are collected and analyzed quarterly.
- Airborne radioiodine and particulate samplers are operated continuously at six locations. Samples are collected and analyzed weekly. Analyses include lodine-131, gross beta, and gamma isotopic measurements.
- Surface water samples are collected from three locations. Samples are collected and analyzed monthly. Analyses include gamma isotopic and tritium measurements.
- Shoreline sediment samples are collected from three locations coinciding with the locations for surface water samples. Samples are collected and analyzed semi-annually. Sediment samples are analyzed by gamma isotopic measurements.
- Fish and invertebrate samples are collected from two locations coinciding with two of the locations for surface water samples. Samples are collected and analyzed semi-annually. Fish and invertebrate samples are analyzed by gamma isotopic measurements.
- Broad leaf vegetation samples are collected from three locations. Samples are collected and analyzed monthly. Broad leaf vegetation samples are analyzed by gamma isotopic measurements.

Table 1 through 4 provides specific information pertaining to sample locations, types, and frequencies.

Note: Ground Water Protection, NEI Initiative: The program and results are described in Attachment 4.

2.2 Pathways Monitored

The airborne, direct radiation, waterborne and ingestion pathways are monitored as required by Control 5.1 of Turkey Point Unit 3 & 4 ODCM. A description of the REMP utilized to monitor the exposure pathways is described in the attached Tables and Figures.

Section 4.0 of this report provides a discussion of 2022 sampling results with Section 5.0 providing a summary of results for the monitored exposure pathways.

2.3 Land Use Census

PTN conducts a land use census, as required by Turkey Point Units 3 & 4 ODCM. The purpose of this census is to identify changes in uses of land within five miles of PTN that would require modifications to the REMP and the Offsite Dose Calculation Manual (ODCM). Section 4.5 on the report contains a narrative on the results of the 2022 land use census.

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 9 of 56

Annual Radiological Environmental Operating Report

3.0 RADIOLOGICAL ENVIRONMENTAL SAMPLING PROGRAM REQUIREMENTS

Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
RADIOIODINE AND PARTICULATES 5 sample indicator locations and 1 sample control location.	 T51 (2 mi. NNW) – Entrance Area to Biscayne National Park. T57 (4 mi. NW) – Siren Pole 27, intersection of SW 112th Ave and SW 304th St. T58 (1 mi. NW) – Turkey Point Entrance Road. T72 (<1 mi. WSW) – Just before entrance to Land Utilizations access gate. T41 (1.6 mi. WNW) – Palm Dr. West of FPL Satellite School near the site boundary. T64* (22 mi. NNE) – Natoma Substation, 2475 SW 16 Ct. 	Continuous sampler operation with sample collection weekly or more frequently if required by dust loading.	 Radioiodine Canisters – I-131 analysis weekly. Air Particulate – Gross beta radioactivity analysis following filter change. Air Particulate – Gamma Isotopic analysis quarterly.

Table 1: Exposure Pathway – Airborne

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 10 of 56
Annual Radiological Environmental Operating Report		

Table 2: Exposure Pathway – Direct Radiation

Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
TLDS	• N-2 (2 mi N) – Convoy Point		
22 indicator sample locations and 1 control sample location.	 N-7 (7.1 mi N) – Black Point Marina parking lot on siren pole 	Quarterly	mR exposure quarterly.
	 N-10 (10.6 mi N) – Old Cutler Rd across from Perdue Med. Ctr. On siren pole. 		
	 NNW-2 (2.2 mi NNW) – East End of N. Canal Dr. on siren pole E. of 117th Ave. 		
	• NNW-10 (9.2 mi NNW) – Bailes Rd. E. of US 1 on siren pole.		
	 NW-1 (1.4 mi NW) – Turkey Point Entrance Rd. 		
	 NW-5 (3.9 mi NW) – Intersection of Mowry Dr. and 117th Ave. on siren pole. 		
	 NW-10 (10 mi NW) – On Newtown Rd. N. of Coconut Palm Drive on siren pole. 		
	 W-5 (5.3 mi W) – Palm Drive 0.3 mi west of Tallahassee Rd. 		
	• WNW-10 (9.8 mi WNW) – NW 2 nd Ave. S. of Campbell Dr. at Hmstd. Middle School on siren pole.		
	• W-1 (0.7 mi W) – On site north side of Discharge Canal.		

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 11 of 56
---	------------	---------------

Table 2: Exposure Pathway – Direct Radiation

Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
TLDS (Cont'd) 22 indicator sample locations and 1 control sample location.	 and Direction W-9 (8.6 mi W) – Card Sound Rd. 0.6 mi SSE of US 1 on siren pole. WSW-8 (7.8 mi WSW) – Card Sound Rd. 3.4 mi. SSE of US 1 on siren Pole. SW-1 (1 mi SW) – On site near land utilization offices. SSE-1 (1 mi SSE) – On site South East side of cooling canals at "Turtle Point". SW-8 (8 mi SW) – Card Sound Rd. 5 mi. SSE of US 1 at entrance to Navy facility. SSW-5 (5 mi SSW) – On site, southwest corner of cooling canals. SSW-10 (10 mi SSW) – At Card Sound Bridge on siren pole. S-5 (5 mi S) – On site, south east end of cooling canals. SSE-10 (10 mi S) – Card Sound Road at Steamboat Creek. SSE-10 (9 mi SSE) – Ocean Reef. NNE-22* (22.6 mi NNE) – Natoma Substation. WNW2 (1.6 mi WNW) – Palm Dr. West of FPL Satellite School, near Site Boundary. 	Quarterly	mR exposure quarterly.

Year: 2022

Page 12 of 56

Annual Radiological Environmental Operating Report

Table 3: Exposure Pathway – Waterborne

Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
SURFACE WATER 2 indicator sample locations and 1 control sample location.	 T42 (<1 mi. ENE) – Biscayne Bay at Turkey Point. T81 (6 mi. S) – Card Sound, near Mouth of Old Discharge Canal. T67* (13-18 mi. N, NNE) – Near Biscayne Bay, Vicinity of Cutler Plant, North to Matheson Hammock Park 	Grab samples Monthly	Gamma isotopic analysis and tritium analysis monthly.
SEDIMENT FROM SHORELINE 2 indicator sample locations and 1 control sample location. Locations coincide with the surface water sample locations.	 T42 (<1 mi ENE) – Biscayne Bay at Turkey Point. T81 (6 mi. S) – Card Sound, near Mouth of Old Discharge Canal. T67* (13-18 mi. N, NNE) – Near Biscayne Bay, Vicinity of Cutler Plant, North to Matheson Hammock Park 	Semi-annually	Gamma isotopic analysis semi-annually.

Year: 2022

Page 13 of 56

Annual Radiological Environmental Operating Report

Table 4: Exposure Pathway – Ingestion

Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
 CRUSTACEA AND FISH 1 indicator sample location and 1 control sample location. 	 T81 (6 mi. S) – Card Sound, near Mouth of Old Discharge Canal. T67* (13-18 mi. N, NNE) – Near Biscayne Bay, Vicinity of Cutler Plant, North to Matheson Hammock Park 	Semi-annually	Gamma isotopic analysis semi-annually.
 BROADLEAF VEGATATION 2 indicator sample locations and 1 control sample location. 	 T40 (3 mi W) – South of Palm Dr. on S.W. 117th Street Extension. T41 (2 mi WNW) – Palm Dr. West of FPL Satellite School near the site boundary. T67* (13-18 mi. N, NNE) – Near Biscayne Bay, Vicinity of Cutler Plant, North to Matheson Hammock Park 	Monthly	Gamma isotopic analysis monthly.

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 14 of 56Annual Radiological Environmental Operating Report



Figure 1: Sample Collection Sites – Near Station

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 15 of 56Annual Radiological Environmental Operating Report




Figure 2: Sample Collection Sites – Distant from Station


4.0 INTERPRETATION AND TRENDS OF RESULTS

4.1 <u>Air Particulate and Radioiodine Sample Results</u>

In 2022 there were no samples above the LLD for I-131. Indicator gross beta air particulate results for 2022 were comparable to results obtained from 2019-2021 of the operational REMP. Results are reported in picocuries per cubic meter (pCi/m³).


Monitoring Period	<u>Result</u>
2019 – 2021 (Minimum Value)	0.002
2022 Average Value	0.013
2019 – 2021 (Maximum Value)	0.030

Gross beta activity is attributed to naturally occurring radionuclides. Table 6, which include gross beta concentrations and provide a comparison of the indicator and control means and ranges emphasizes the consistent trends seen in this pathway to support the presence of naturally occurring activity. Figure 3 is a comparison of the weekly Gross Beta results for 2022. Therefore, it can be concluded that the airborne pathway continues to be unaffected by Turkey Point Nuclear operations.



4.2 <u>Thermoluminescent Dosimetry (TLD) Sample Results</u>

Turkey Point Nuclear reports relies on comparison of the indicator locations to the control as a measure of plant impact. Turkey Point Nuclear's comparison of the indicator to the control, as seen in Table 6, identified no noticeable trend that would indicate that the ambient radiation levels are being affected by plant operations. In addition, the quarterly indicator averages shown in the TLD radiation dose comparison graph below shows the 2022 indicator results are comparable to control location results. Overall, Turkey Point Nuclear concluded that the ambient radiation levels are not being affected by plant operations.



4.3 Waterborne Sample Results

Analytical results for 2022 surface water samples were similar to those reported in previous years. Gamma radionuclides and tritium analytical results for 2022 waterborne samples were below the ODCM-required LLD similar to those reported in previous years. These results are further explained below.

4.3.1 Surface Water Results

Samples were collected from two indicator and one control location and analyzed for gamma radionuclides and tritium. Tritium was detected in 1 out of 24 indicator location samples with a concentration of 84 pCi/L which is consistent with results seen in previous operational years. There were no plant related gamma radionuclides detected in any of the control or indicator location samples. Therefore, the operation of Turkey Point Nuclear had no definable impact on this waterborne pathway during 2022.

4.3.2 Shoreline Sediment Sample Results

Sediment samples were collected from two indicators and one control location in 2022 and analyzed for gamma radionuclides. Plant related gamma radionuclides were below the LLD limits at both indicator and control locations. Turkey Point Nuclear operations had no significant impact on the environment or public by this waterborne pathway.

4.4 Ingestion Sample Results

4.4.1 Crustacea and Fish Sample Results

Crustacea and Fish samples were collected from one indicator and one control location and analyzed for gamma radionuclides. In 2022, gamma radionuclides were below detectable limits which are consistent with the results seen in previously operational years. Therefore, based on these measurements, Turkey Point Nuclear operations had no significant radiological impact upon the environment or public by this ingestion pathway.

4.4.2 Broad Leaf Vegetation Sample Results

The REMP had detected radionuclides prior to 1990 in vegetation that are attributable to other sources. These include the radioactive plume release due to reactor core degradation at Chernobyl Nuclear Power Plant in 1986 and atmospheric weapons testing.

In 2022, Broad Leaf Vegetation samples were collected from two indicator and one control locations and analyzed for gamma radionuclides. The 2022 Cs-137 was detected in samples collected from the indicator and control locations. This activity identified could be from weapons fallout testing 30-40 years ago and reactor accidents at Chernobyl and are contributors. Therefore, based on these measurements, Turkey Point Nuclear operations had no significant radiological impact upon the environment or public by this ingestion pathway.

4.5 Land Use Census Results

The latest land use census (performed in 2022) did not identify any new locations that yielded a calculated dose or dose commitment greater than those currently calculated (see Table 5).

The land use census identified no changes in the new resident census.

There were no changes in the milk cows/goats or garden census in 2022.

Table 5: Land Use Census –2022 Nearest Residence, Garden, and Milk Animal Within Five Miles

SECTOR	NEAREST	NEAREST	NEAREST
	RESIDENCE/BUSINESS	GARDEN (A)	MILK ANIMAL
Ν	1.9 mi @ 349°	*	*
	1.98 mi @ 349°		
	2.0 mi @ 354°		
NNE	*	*	*
NE	*	*	*
ENE	*	*	*
E	*	*	*
ESE	*	*	*
SE	*	*	*
SSE	*	*	*
S	*	*	*
SSW	*	*	*
SW	*	*	*
WSW	*	*	*
W	*	*	*
WNW	1.7 mi @ 302°	4.5 mi @ 303°	*
	3.7 mi @ 302°	6.0 mi @ 295°	
NW	3.6 mi @ 304°	*	*
	3.7 mi @ 311°		
	3.8 mi @ 316°		
	3.9 mi @ 314°		
NNW			*
	4.4 mi @ 333°	4.4 mi @ 332°	
	4.7 mi @ 328°	4.7 mi @ 328°	

(A) - Only gardens with an estimated total area of 500 square feet, or more, and producing green leafy vegetables are considered.

* - No suitable sites were located within a five-mile range.

Year: 2022

Annual Radiological Environmental Operating Report

TURKEY POINT RESIDENCE SURVEY RESULTS

July 2022

Sector	Range	Nearest Residence/Business Location						
N (A)	Bearing <u>1.9 miles</u> 349°	Homestead Bayfront Park complex. Contact is Jim Wyath. Office hours are 8:30 to 4:30, 7 days a week. Some occasional overnight recreational occupancy (up to 4 nights) on boats at the marina. Approximately 10 workers, 7 days a week, hours and numbers vary. Some summer weekends can see 1000+ visitors. There is always someone here 24 hours with more workers in the summer than the rest of the year (February thru September have the highest peak of workers). LaPlaya restaurant is open at the park weekdays from 11 am to 8:30 pm with 8 to 10 employees. Weekends open till 10 pm and may have up to 15 employees. N25° 27.683' W80° 20.200'.						
N (B)	<u>1.98 miles</u> 349°	South Glade Outfitters. Located on opposite side of building from office of Homestead Bayfront Park. Manager is Robert and have 2-3 employees. Weekdays 7 am to 5 pm, Fridays till 6 pm. Weekends 7 am – 6 pm. Hours may vary depending on weather. N25° 27.767' W80° 20.206'.						
N (C)	<u>2.0 miles</u> 354°	Biscayne National Park at Convoy Point. Open 7 am to 5:30 pm everyday. There are 65 employees including volunteers and individuals at the institute. The one ranger and two seasonal employees are there all year. There are about 500,000 visitors (more including boaters) per year. Contacts include: Michelle Penick, Chief of Facilities, J. Ernest Jutte, Chief of Administration, 305-242-7721 (office) 202-438-6636 (mobile), and Cindy Holl (administrator) 239-695-1114. N25° 27.817' W80° 20.067'.						
NNE	No residences we	No residences were located within a five-mile range.						
NE	No residences we	No residences were located within a five-mile range.						
ENE	No residences we	ere located within a five-mile range.						
Е	No residences we	No residences were located within a five-mile range.						
ESE	No residences we	ere located within a five-mile range.						
SE	No residences we	No residences were located within a five-mile range.						
SSE	No residences we	No residences were located within a five-mile range.						
S	No residences we	ere located within a five-mile range.						
SSW	No residences we	ere located within a five-mile range.						
SW	No residences we	ere located within a five-mile range.						
WSW	No residences we	ere located within a five-mile range.						
W	No residences we	No residences were located within a five-mile range.						

Year: 2022

Annual Radiological Environmental Operating Report

TURKEY POINT RESIDENCE SURVEY RESULTS

July 2022 (cont.)

Sector	<u>Range</u> Bearing	Nearest Residence/Business Location
WNW (A)	<u>1.7 miles</u> 302°	FP&L daycare center and shooting range near the entrance to the Turkey Point Plant. Contact is Yudisvel "Judy" Diaz, Director. There are 15 employees with 90 children currently enrolled, ages 6 months to 5 yrs. Occasionally, they will have school aged children. The center is open from 6am to 6pm Monday thru Friday. The number of people and times at the shooting range varies. N25° 26.817' W80° 21.217'.
WNW (B)	<u>3.7 miles</u> 302°	11790 Canal Drive on the south side of Canal Drive (SW 328 St) west of SW 117th Ave (no gardens). Next door, to the east, is a makeshift produce stand which sells coconuts, limes, mandarin oranges, flowers, garlic, mangoes, papaya, avocado, honey, melons, sugar cane, ginger, plantains and pumpkins. Is not associated with the house next door. Two employees may be working there from 8 am to 6 pm. N25° 27.767' W80° 22.867'.
NW (A)	<u>3.6 miles</u> 304°	The Waste Management Homestead Landfill is located north of Canal Drive (SW 328th St) and east of SW 117th Ave. There are 9 full time employees onsite Monday thru Friday from 7 am to 3:30 pm. N25° 27.833' W80° 22.767'.
NW (B)	<u>3.7 miles</u> 311°	11000 SW 320th St. Per property records, this house is on land zoned agriculture and the owners live in Texas. Unable to verify if anyone lives there because the gate is locked and the residence is too far from the road to see anything. N25° 28.217' W80° 22.567'.
NW (C)	<u>3.8 miles</u> 316°	High Hope Nursery at 11400 SW 316th St. Contact is George Sprinkle, Owner and General Manager. This nursery has approximately 35 employees. Hours of operations are 7am to 5pm Monday thru Friday, with some work on Saturdays until noon. A man lives onsite providing security. N25° 28.441' W80° 22.430'.
NW (D)	<u>3.9 miles</u> 314°	Snapper Creek Nursery at 11600 SW 316th Street. 14 workers that work Monday thru Friday 7 am to 5 pm. Contact is Elmer. Security is provided by another person who lives onsite. N25° 28.444' W80° 22.560'.
NNW (A)	<u>4.4 miles</u> <u>333°</u>	29800 SW 107th Ave. Per property records, this is a small one bedroom residence on land zoned as mixed use agricultural. No information on occupants. N25° 29.450' W80° 21.817'.
NNW (B)	<u>4.7 miles</u> <u>328°</u>	Mirtica and Sons Dragon Fruit Farm. Entrance at the end of SW 296th St. Contact is Ernesto Gonzalez Abreu. Owner lives off property in Miami N25° 29.564' W80° 22.264'.

Annual Radiological Environmental Operating Report

TURKEY POINT GARDEN SURVEY RESULTS

July 2022

Sector	<u>Range</u> Bearing	Nearest Garden Location (with estimated total area of 500 square feet, or more, and producing green leafy vegetables).						
Ν	No suitable garden	s were located within a five-mile range.						
NNE	No suitable garden	s were located within a five-mile range.						
NE	No suitable garden	s were located within a five-mile range.						
ENE	No suitable garden	s were located within a five-mile range.						
Е	No suitable garden	s were located within a five-mile range.						
ESE	No suitable garden	s were located within a five-mile range.						
SE	No suitable garden	s were located within a five-mile range.						
SSE	No suitable garden	No suitable gardens were located within a five-mile range.						
S	No suitable garden	s were located within a five-mile range.						
SSW	No suitable garden	s were located within a five-mile range.						
SW	No suitable garden	s were located within a five-mile range.						
WSW	No suitable garden	No suitable gardens were located within a five-mile range.						
W	No suitable garden	s were located within a five-mile range.						

Year: 2022

Annual Radiological Environmental Operating Report

TURKEY POINT GARDEN SURVEY RESULTS

July 2022 (cont.)

Sector	<u>Range</u> Bearing	Nearest Garden Location (with estimated total area of 500 square feet, or more, and producing green leafy vegetables).
WNW (A)	<u>4.5 miles</u> 303°	Thai Farm. South of Mowry Drive (SW 320th St) and about 0.6 miles west of Allapattah Rd (SW 117th Ave). Growing guava, dragon fruit, papaya, palm, bamboo, and more. No one present. N25° 28.217' W80° 23.467'.
WNW (B)	<u>6.0 miles</u> 295°	Farm Share, Inc at 14125 SW 320th St, where farmers donate locally grown produce to be given to charitable organizations. Produce donations usually start in November and run through April. About 20 workers present from 8 am to 4:30 pm Monday thru Friday. The produce donated is usually tomatoes, bananas, squash, green beans, okra, corn, potatoes, watermelon and zucchini. N25° 28.255' W80° 25.111'.
NW	No suitable gardens	were located within a five-mile range.
NNW (A)	<u>4.4 miles</u> 332°	Under the Vine. 11100 SW 296th St. Entrance at SW 107th Ave & SW 296th St just east of SFM Tree Farm/Mirtica Farm. Growing only dragon fruit. Open Mon-Sat 8:00-5:00. 3 employees plus the owner, Cindy, work here. Sometimes they hire extra help. The owner's brother, Pepper, sometimes spends the weekends onsite. N25° 29.464' W80° 21.828'.
NNW (B)	<u>4.7 miles</u> 328°	Now Mirtica and Sons Dragon Fruit Farm. Entrance at the end of SW 296th St. Noticed bananas, dragon fruit, plantain tress, coconuts and mangoes growing in various areas on the farm. Also noticed beehives. Owner lives off property in Miami. N25° 29.564' W80° 22.264'.

Note: At the time of our survey, many fields in the area surveyed were bare soil or cover crops. Other than the sites already described above, the only non-ornamental crops known to have been grown in the survey area were: bananas, beans, corn, guava, malanga, papaya, eggplant, sorghum, squash, sugar cane, tambis, okra, and melon.

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 24 of 56Annual Radiological Environmental Operating Report

TURKEY POINT MILK ANIMAL SURVEY RESULTS

July 2022

Sector	Nearest Milk Animals (cows or goats).
Ν	No potential milk animals were located within five miles.
NNE	No potential milk animals were located within five miles.
NE	No potential milk animals were located within five miles.
ENE	No potential milk animals were located within five miles.
Е	No potential milk animals were located within five miles.
ESE	No potential milk animals were located within five miles.
SE	No potential milk animals were located within five miles.
SSE	No potential milk animals were located within five miles.
S	No potential milk animals were located within five miles.
SSW	No potential milk animals were located within five miles.
SW	No potential milk animals were located within five miles.
WSW	No potential milk animals were located within five miles.
W	No potential milk animals were located within five miles.
WNW	No potential milk animals were located within five miles.
NW	No potential milk animals were located within five miles.
NNW	No potential milk animals were located within five miles.

4.6 Interlaboratory Comparison Results

Attachment 3 contains result summary for Interlaboratory Comparison Program for the Department of Energy Mixed Analyte Performance Evaluation Program (MAPEP). These satisfied the requirement of Control 5.3 of the ODCM for the Interlaboratory Comparison Program.

5.0 RADIOLOGICAL ENVIRONMENTAL MONITORING PROGRAM SUMMARY

1. Table 6, Radiological Environmental Monitoring Program Summary, summarizes data for the 2022 REMP program.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 26 of 56

Sample Type (Units)	Type / Number of Analyses ⁽¹⁾	LLD ⁽²⁾	Indicator Locations Mean (F) ⁽³⁾ [Range]	Location ⁽⁴⁾ [Highest Annual Mean]	Mean (F) ⁽³⁾ [Range]	Control Locations Mean (F) ⁽³⁾ [Range]	Number of Non Routine Results ⁽⁵⁾
	GB / 296	0.01	0.0127 (243 / 260)	T64	0.0135 (50 / 52)	0.0135 (50 / 52)	0
Air Particulate (pCi/m³)	GS / 24 Be-7		[0.003 - 0.024] 0.1076 (20 / 20) [0.059 - 0.146]	(22 mi. NNE) T58 (1 mi. NW)	[0.003 - 0.024] 0.1204 (4 / 4) [0.0837 - 0.146]	[0.003 - 0.024] 0.1082 (4 / 4) [0.0829 - 0.135]	0
	K-40 Cs-134 Cs-137	 0.05 0.06	< LLD < LLD < LLD	N/A N/A N/A	N/A N/A N/A	< LLD < LLD < LLD	0 0 0
	Pb-210		0.009 (2 / 20) [0.0086 - 0.0093]	T58 (1 mi. NW)	0.0093 (1 / 4) [<lld -="" 0.0093]<="" td=""><td>< LLD</td><td>0</td></lld>	< LLD	0
Airborne lodine (pCi/m³)	I-131 / 296	0.07	< LLD	N/A	N/A	< LLD	0
Direct Radiation Indicator TLD (μR/hour)	Gamma / 88	(6)	3.8 (88 / 88) [2.8 - 5.1]	NW-10 (10 mi NW)	4.4 (4 / 4) [3.4 - 5.1]	N/A	0
Direct Radiation Control TLD (μR/hour)	Gamma / 4	(6)	N/A	NNE-22 (22.6 mi NNE)	3.7 (4 / 4) [3.1 - 4.4]	4 (4 / 4) [3.7 - 4.2]	0

LEGEND:

(1) - GB = Gross beta; I-131 = Iodine-131; H-3 = Tritium; GS = Gamma scan.
 (2) - LLD = Required lower limit of detection based on Turkey Point ODCM.
 (3) - Mean and range based upon detectable measurements only. Fraction of detectable measurements at specified locations is indicated in parenthesis (F).
 (4) - Locations are specified (1) by name and (2) direction relative to reactor site.

⁽⁵⁾ - Non-routine results are those which exceed ten times the control station value. If no control station value is available, the result is considered non-routine if it exceeds ten times the preoperational value for the location.

⁽⁶⁾ - LLD is not defined in Turkey Point ODCM.

Year: 2022

Page 27 of 56

Annual Radiological Environmental Operating Report

Sample Type (Units)	Type / Number of Analyses ⁽¹⁾	LLD ⁽²⁾	Indicator Locations Mean (F) ⁽³⁾ [Range]	Location ⁽⁴⁾ [Highest Annual Mean]	Mean (F) ⁽³⁾ [Range]	Control Locations Mean (F) ⁽³⁾ [Range]	Number of Non Routine Results ⁽⁵⁾
	H-3 / 36	3,000	84 (1 / 24)	T42	84 (1 / 12)	< LLD	0
Surface Water			[<lld -="" 84]<="" td=""><td>(<1 mi. ENE)</td><td>[<lld -="" 84]<="" td=""><td></td><td></td></lld></td></lld>	(<1 mi. ENE)	[<lld -="" 84]<="" td=""><td></td><td></td></lld>		
(pCi/L)	GS / 36						
(pone)	K-40		292 (24 / 24)	T81	304 (12 / 12)	213 (12 / 12)	0
			[193 - 398]	(6 mi S)	[237 - 386]	[127 - 298]	
	GS / 6						
	Be-7		80 (1 / 4)	T67	116 (1 / 2)	116 (1 / 2)	0
			[<lld -="" 80]<="" td=""><td>(13-18 mi N, NNE)</td><td>[<lld -="" 116]<="" td=""><td>[<lld -="" 116]<="" td=""><td></td></lld></td></lld></td></lld>	(13-18 mi N, NNE)	[<lld -="" 116]<="" td=""><td>[<lld -="" 116]<="" td=""><td></td></lld></td></lld>	[<lld -="" 116]<="" td=""><td></td></lld>	
Sediment (pCi/kg dry)	K-40		170 (3 / 4) [122 - 224]	T67 (13-18 mi N, NNE)	382 (2 / 2) [102 - 662]	382 (2 / 2) [102 - 662]	0
	Cs-137	180	< LLD	N/A	N/A	< LLD	0
	Pb-210		< LLD	N/A	N/A	< LLD	0
	Ra-226		408 (4 / 4) [332 - 487]	T67 (13-18 mi N, NNE)	449 (1 / 2) [<lld -="" 449]<="" td=""><td>449 (1 / 2) [<lld -="" 449]<="" td=""><td>0</td></lld></td></lld>	449 (1 / 2) [<lld -="" 449]<="" td=""><td>0</td></lld>	0
	Th-232		<lld< td=""><td>N/A</td><td>N/A</td><td>< LLD</td><td>0</td></lld<>	N/A	N/A	< LLD	0
	U-235		42 (3 / 4)	T81	50 (2 / 2)	44 (1 / 2)	0
			[24 - 75]	(6 mi. S)	[24 - 75]	[<lld -="" 44]<="" td=""><td></td></lld>	
	U-238		179 (4 / 4) [132 - 238]	T67 (13-18 mi N, NNE)	563 (1 / 2) [<lld -="" 563]<="" td=""><td>563 (1 / 2) [<lld -="" 563]<="" td=""><td>0</td></lld></td></lld>	563 (1 / 2) [<lld -="" 563]<="" td=""><td>0</td></lld>	0

Table 6: Radiological Environmental Monitoring Program Summary

LEGEND:

(1) - GB = Gross beta; I-131 = Iodine-131; H-3 = Tritium; GS = Gamma scan.

⁽²⁾ - LLD = Required lower limit of detection based on Turkey Point ODCM.

⁽³⁾ - Mean and range based upon detectable measurements only. Fraction of detectable measurements at specified locations is indicated in parenthesis (F).
 ⁽⁴⁾ - Locations are specified (1) by name and (2) direction relative to reactor site.

⁽⁵⁾ - Non-routine results are those which exceed ten times the control station value. If no control station value is available, the result is considered non-routine if it exceeds ten times the preoperational value for the location.

⁽⁶⁾ - LLD is not defined in Turkey Point ODCM.

Year: 2022

Page 28 of 56

Annual Radiological Environmental Operating Report

Sample Type (Units)	Type / Number of Analyses ⁽¹⁾	LLD ⁽²⁾	Indicator Locations Mean (F) ⁽³⁾ [Range]	Location ⁽⁴⁾ [Highest Annual Mean]	Mean (F) ⁽³⁾ [Range]	Control Locations Mean (F) ⁽³⁾ [Range]	Number of Non Routine Results ⁽⁵⁾
Crustacea	GS / 4 K-40		1550 (2 / 2) [1460 - 1640]	T81	1550 (2 / 2) [1460 - 1640]	1007 (2 / 2) [693 - 1320]	0
(pCi/kg wet)	Ra-226 Ra-228		[1460 - 1640] <lld <lld< td=""><td>(6 mi. S) N/A N/A</td><td>N/A N/A</td><td>[093 - 1320] <lld <lld< td=""><td>0 0</td></lld<></lld </td></lld<></lld 	(6 mi. S) N/A N/A	N/A N/A	[093 - 1320] <lld <lld< td=""><td>0 0</td></lld<></lld 	0 0
	GS / 4			IN/A	IN/A		0
Fish (pCi/kg wet)	K-40		2400 (2 / 2) [2150 - 2650]	T81 (6 mi. S)	2400 (2 / 2) [2150 - 2650]	2400 (2 / 2) [2230 - 2570]	0
(polikg wet)	Ra-226 Ra-228		< LLD < LLD	N/A N/A	N/A N/A	<lld <lld< td=""><td>0 0</td></lld<></lld 	0 0
Broad Leaf (pCi/kg wet)	GS / 36 Be-7		1553 (24 / 24) [579 - 3060]	T40 (3 mi W)	1741 (12 / 12) [925 - 3060]	1110 (12 / 12) [535 - 1830]	0
	K-40		4216 (24 / 24) [2070 - 6350]	T67 (13-18 mi N, NNE)	4733 (12 / 12) [3760 - 5680]	4733 (12 / 12) [3760 - 5680]	0
	Cs-137	80	40. (13 / 24) [10 - 117]	T40 (3 mi W)	43 (10 / 12) [10 - 117]	<lld< td=""><td>0</td></lld<>	0
	Pb-210		408 (6 / 24) [75 - 1610]	T41 (2 mi WNW)	716 (3 / 12) [75 - 1610]	384 (3 / 12) [47 - 562]	0
	Pb-212		< LLD	N/A	N/A	<lld< td=""><td>0</td></lld<>	0
	Ra-226		295 (1 / 12) [<lld -="" 295]<="" td=""><td>T41 (2 mi WNW)</td><td>295 (1 / 12) [<lld -="" 295]<="" td=""><td>219 (1/12) [<lld -="" 219]<="" td=""><td>0</td></lld></td></lld></td></lld>	T41 (2 mi WNW)	295 (1 / 12) [<lld -="" 295]<="" td=""><td>219 (1/12) [<lld -="" 219]<="" td=""><td>0</td></lld></td></lld>	219 (1/12) [<lld -="" 219]<="" td=""><td>0</td></lld>	0

Table 6: Radiological Environmental Monitoring Program Summary

LEGEND:

(1) - GB = Gross beta; I-131 = Iodine-131; H-3 = Tritium; GS = Gamma scan.

⁽²⁾ - LLD = Required lower limit of detection based on Turkey Point ODCM.

⁽³⁾ - Mean and range based upon detectable measurements only. Fraction of detectable measurements at specified locations is indicated in parenthesis (F).

⁽⁴⁾ - Locations are specified (1) by name and (2) direction relative to reactor site.

⁽⁵⁾ - Non-routine results are those which exceed ten times the control station value. If no control station value is available, the result is considered non-routine if it exceeds ten times the preoperational value for the location.

⁽⁶⁾ - LLD is not defined in Turkey Point ODCM.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 29 of 56

Attachment 1

Page 1 of 2

Sample Deviations

Table 7: Sample Deviations Table

Comment No.	Sample Media Affected	Sample Location	Date	Problem	Evaluation / Actions	
1	TLD	ENE-1	2 nd Qtr.	Sample Missing	During routine sampling at locations ENE-1, it was discovered that the TLD was missing. Replacement TLD was installed. AR# 02444644	
2	TLD	NW-8	2 nd Qtr.	Sample Missing	During routine sampling at locations NW-8, it was discovered that the TLD was missing. Replacement TLD was installed. AR# 02444644	
3	Air Sample	T57	06/07/22	Pump Failure	Vacuum pump was replaced on June 7, 2022. The sample pump was replaced and then returned to service upon recognition of the failing pump. AR# 02444644	
4	Air Sample	T72	06/21/22	Power Outage Power outage at station T72. The power was restored for weekly collection of June 21, 2022. AR# 02430654		
		T41		Samples Lost in Shipping	Sample Points T41, T51, T57, T58, T64 & T72-(Radioiodine and Particulates) From August 8th - August 12, 2022; These samples were collected and shipped	
		T51				
5	Air Samples	T57	08/12/22		via FedEx by the BRC technician for Turkey Point Nuclear to their laboratory in Orlando. During transit, the package was damaged, and the filters were lost. The	
		T58 T64			iodine cartridges were not lost and were not analyzed by the lab. The technician reached out numerous times to FedEx to find the filters, but they were unsuccessful. AR# 02444649/AR# 02456863	
		T72				
		T41				
		T51			Sample Points T41, T51, T57, T58, T64 & T72- (Radioiodine and Particulates)	
		T57		Samples Lost in	from September 26 – September 30, 2022: These samples were not collected during the assigned week. They were collected the following week without	
6	Air Samples	T58	09/30/22		incident. The reason for the missed collection was that the BRC technician	
		T64			assigned to Turkey Point resigned unexpectedly and no one was able to collect the samples in a timely fashion. AR# 02444649	
		T72				

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 30 of 56
---	------------	---------------

Attachment 1

Page 2 of 2

Sample Deviations Table 7: Sample Deviations Table

Comment No.	Sample Media Affected	Sample Location	Date Problem		Evaluation / Actions
7	Groundwater	6s and 6d	4 th Qtr.	Relocation	As part of the FPL Miami-Dade Clean Water Recovery Project, two of the site's groundwater monitoring wells were abandoned to avoid damage during CWRC construction. AR# 02438187
8	Milk	Т99	2022	Sample Unavailable	Goat milk sample was unavailable this year. The farm has not had any milking goats. AR# 02447728

ATTACHMENT 2

Monitoring Results Tables

RADIOLOGICAL SURVEILLANCE OF FLORIDA POWER AND LIGHT COMPANY'S

TURKEY POINT SITE 2022

First Quarter, 2022 Second Quarter, 2022 Third Quarter, 2022 Fourth Quarter, 2022

Plant: Turkey Point Nuclear Units 3 & 4	2022	Page 32 of 56			
Annual Radiological Environmental Operating Report					

Attachme	ent 2	

Monitoring Results Tables

Page 1 of 16

Table 8: Air Particulate - Gross Beta								
	Analys	is: Gross Beta		Units: pCi/m ³				
End Data	T41	T51	T57	T58	T64	$\mathbf{T}_{\mathbf{T}}\mathbf{O}^{(1)}$ (in dia star)		
End Date	(Indicator)	(Indicator)	(Indicator)	(Indicator)	(Control)	T72 ⁽¹⁾ (Indicator)		
LLD 🗲	<u>0.01</u>	<u>0.01</u>	<u>0.01</u>	<u>0.01</u>	<u>0.01</u>	<u>0.01</u>		
01/06/2022	0.014	0.015	0.014	0.014	0.015	0.018		
01/12/2022	0.014	0.013	0.018	0.018	0.020	0.016		
01/19/2022	0.021	0.014	0.024	0.016	0.015	0.018		
01/27/2022	0.009	0.015	0.014	0.015	0.016	0.014		
02/02/2022	0.016	0.010	0.016	0.017	0.015	0.014		
02/09/2022	0.011	0.013	0.013	0.014	0.011	0.008		
02/15/2022	0.017	0.018	0.014	0.021	0.019	0.014		
02/24/2022	0.012	0.013	0.012	0.014	0.012	0.016		
03/02/2022	0.004	0.011	< 0.183	0.005	0.006	0.010		
03/07/2022	0.013	0.013	0.012	0.016	0.010	0.009		
03/16/2022	0.005	0.007	0.008	0.010	0.010	0.009		
03/23/2022	0.012	0.013	0.009	0.012	0.012	0.009		
03/30/2022	0.021	0.017	0.020	0.018	0.020	0.020		
04/05/2022	0.012	0.013	0.015	0.016	0.015	0.014		
04/13/2022	0.015	0.013	0.013	0.012	0.018	0.014		
04/19/2022	0.008	0.010 0.016	0.011 0.017	0.011 0.014	0.007	0.007		
04/27/2022	0.013	0.016	0.017	0.014	0.013	0.015		
05/11/2022	0.015	0.013	0.017	0.011	0.012	0.013		
05/17/2022	0.013	0.010	0.007	0.008	0.009	0.014		
05/24/2022	0.017	0.024	0.012	0.014	0.020	0.010		
05/31/2022	0.020	0.024	0.012	0.021	0.020	(3)		
06/06/2022	0.005	0.003	0.005	0.008	0.003	(3)		
06/14/2022	0.012	0.013	(2) 0.010	0.014	0.013	(3)		
06/21/2022	0.011	0.023	0.017	0.018	0.019	(3)		
06/27/2022	0.017	0.020	0.014	0.014	0.015	0.017		
07/04/2022	0.010	0.008	0.006	0.012	0.006	0.010		
07/12/2022	0.009	0.013	0.007	0.008	0.009	0.011		
07/19/2022	0.007	0.013	0.011	0.014	0.013	0.016		
07/26/2022	0.011	0.017	0.012	0.018	0.014	0.015		
08/01/2022	0.013	0.012	0.015	0.012	0.012	0.014		
08/09/2022	(4)	(4)	(4)	(4)	(4)	(4)		
08/16/2022	0.021	0.014	0.015	0.013	0.020	0.023		
08/23/2022	0.010	0.011	0.006	0.011	0.017	0.011		
09/06/2022	0.006	0.006	0.007	0.006	0.008	0.007		
09/14/2022	0.004	0.008	0.007	0.006	0.007	0.004		
09/20/2022	0.011	0.009	0.007	0.007	0.007	0.015		
09/26/2022	0.019	0.019	0.017	0.020	0.022	0.023		
09/30/2022	(5)	(5)	(5)	(5)	(5)	(5)		
10/04/2022	0.005	0.005	0.004	0.003	0.005	0.004		
10/11/2022	0.016	0.013	0.012	0.013	0.013	0.012		
10/19/2022	0.010	0.010	0.013	0.011	0.016	0.013		
10/25/2022	0.015	0.016	0.015	0.017	0.021	0.019		
10/31/2022	0.010	0.016	0.010	0.010	0.014	0.014		
11/09/2022	0.010	0.015 0.005	0.010 0.008	0.011	0.013	< 0.009		
11/15/2022 11/21/2022	0.006	0.005	0.008	0.006 0.007	0.009 0.011	< 0.002		
11/21/2022	0.006	0.005	0.008	0.007	0.007	0.002		
12/06/2022	0.009	0.008	0.010	0.009	0.007	0.011		
12/06/2022	0.009	0.015	0.013	0.013	0.018	0.013		
	0.015	0.017	0.018	0.018	0.013	0.018		
12/21/2022								

⁽¹⁾ Station with highest annual mean.

⁽²⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 3

⁽³⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 4

⁽⁴⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 5

⁽⁵⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 6

Year: 2022

Page 33 of 56

Annual Radiological Environmental Operating Report

Attachment 2

Page 2 of 16

Monitoring Results Tables

Table 9: Air Particulate Composite - Gamma

Ana	lysis: Gamma Isotop	oic		Units: pCi/m ³				
Location	Collection Date	Be-7	K-40	Cs-134	Cs-137	Pb-210		
	REQUIRED LLD 🗲			<u>0.05</u>	0.06			
T41 (Indicator)	03/30/2022	0.1330	< 0.013	3 < 0.0011	< 0.0008	0.0086		
T51 (Indicator)	03/30/2022	0.1150	< 0.014	7 < 0.0009	< 0.0008	< 0.0330		
T57 (Indicator)	03/30/2022	0.1270	< 0.014	6 < 0.0011	< 0.0010	< 0.0145		
T58 (Indicator)	03/30/2022	0.1460	< 0.013	3 < 0.0010	< 0.0010	0.0093		
T64 (Control)	03/30/2022	0.1350	< 0.0143	3 < 0.0010	< 0.0008	< 0.0143		
T72 (Indicator)	03/30/2022	0.1300	< 0.016	3 < 0.0010	< 0.0008	< 0.0327		
T41 (Indicator)	06/27/2022	0.1410	< 0.021	1 < 0.0010	< 0.0011	< 0.0355		
T51 (Indicator)	06/27/2022	0.0996	< 0.0134	4 < 0.0012	< 0.0011	< 0.0121		
T57 (Indicator)	06/27/2022	0.1220	< 0.014	9 < 0.0011	< 0.0007	< 0.0351		
T58 (Indicator)	06/27/2022	0.1400	< 0.013) < 0.0014	< 0.0009	< 0.0113		
T64 (Control)	06/27/2022	0.1150	< 0.0173	3 < 0.0011	< 0.0010	< 0.0334		
T72 (Indicator)	06/27/2022	0.1210	< 0.021	7 < 0.0019	< 0.0014	< 0.0161		
T41 (Indicator)	09/30/2022	0.0590	< 0.012	6 < 0.0010	< 0.0009	< 0.0096		
T51 (Indicator)	09/30/2022	0.0849	< 0.012	7 < 0.0010	< 0.0009	< 0.0306		
T57 (Indicator)	09/30/2022	0.0709	< 0.012	7 < 0.0010	< 0.0009	< 0.0095		
T58 (Indicator)	09/30/2022	0.0837	< 0.015) < 0.0007	< 0.0008	< 0.0310		
T64 (Control)	09/30/2022	0.0829	< 0.012	5 < 0.0008	< 0.0008	< 0.0105		
T72 (Indicator)	09/30/2022	0.0664	< 0.012	6 < 0.0011	< 0.0010	< 0.0110		
T41 (Indicator)	12/28/2022	0.0801	< 0.015	5 < 0.0008	< 0.0007	< 0.0324		
T51 (Indicator)	12/28/2022	0.1120	< 0.017	2 < 0.0009	< 0.0009	< 0.0095		
T57 (Indicator)	12/28/2022	0.1080	< 0.010	7 < 0.0007	< 0.0009	< 0.0275		
T58 (Indicator)	12/28/2022	0.1120	< 0.022	2 < 0.0008	< 0.0010	< 0.0072		
T64 (Control)	12/28/2022	0.1000	< 0.012	1 < 0.0006	< 0.0008	< 0.0325		
T72 (Indicator)	12/28/2022	0.1010	< 0.0194	4 < 0.0008	< 0.0008	< 0.0056		

⁽²⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 3

⁽³⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 4

⁽⁴⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 5

⁽⁵⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 6

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 34 of 56				
Annual Radiological Environmental Operating Report						

. . .

Attachment 2

Monitoring Results Tables

Page 3 of 16

Table 10: Air Cartridges - Iodine-131								
	Analys	sis: lodine-131		Units: pCi/m ³				
– 15 (T41		T51	T57	T58	T64	T72		
End Date	(Indicator)	(Indicator)	(Indicator)	(Indicator)	(Control)	(Indicator)		
LLD 🗲	<u>0.07</u>	<u>0.07</u>	<u>0.07</u>	<u>0.07</u>	<u>0.07</u>	<u>0.07</u>		
01/06/2022	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010		
01/12/2022	< 0.020	< 0.030	< 0.030	< 0.020	< 0.030	< 0.030		
01/19/2022	< 0.010	< 0.020	< 0.020	< 0.010	< 0.010	< 0.020		
01/27/2022	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010		
02/02/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
02/09/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
02/15/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
02/24/2022	< 0.020	< 0.020	< 0.030	< 0.020	< 0.020	< 0.020		
03/02/2022	< 0.020	< 0.020	< 0.690	< 0.020	< 0.020	< 0.020		
03/07/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
03/16/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
03/23/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
03/30/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
04/05/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
04/13/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
04/19/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.020	< 0.030		
04/27/2022	< 0.020 < 0.010	< 0.010 < 0.010	< 0.010 < 0.010	< 0.010 < 0.010	< 0.010	< 0.010		
05/02/2022 05/11/2022	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010 < 0.020	< 0.010 < 0.020		
05/17/2022	< 0.020	< 0.020	< 0.030	< 0.020	< 0.020	< 0.020		
05/24/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.080		
05/31/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	(3)		
06/06/2022	< 0.020	< 0.020	< 0.020	< 0.030	< 0.030	(3)		
06/14/2022	< 0.030	< 0.030	⁽²⁾ < 0.030	< 0.020	< 0.030	(3)		
06/21/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	(3)		
06/27/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
07/04/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
07/12/2022	< 0.030	< 0.030	< 0.030	< 0.020	< 0.030	< 0.030		
07/19/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
07/26/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
08/01/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
08/09/2022	(4)	(4)	(4)	(4)	(4)	(4)		
08/16/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
08/23/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.030		
09/06/2022	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010		
09/14/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.030		
09/20/2022	< 0.020	< 0.030	< 0.020	< 0.020	< 0.020	< 0.020		
09/26/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
09/30/2022	(5)	(5)	(5)	(5)	(5)	(5)		
10/04/2022	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010		
10/11/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
10/19/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
10/25/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
10/31/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
11/09/2022	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
11/15/2022	< 0.030	< 0.030 < 0.030	< 0.030 < 0.030	< 0.030 < 0.030	< 0.020 < 0.030	< 0.030 < 0.030		
11/21/2022	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030		
11/30/2022 12/06/2022	< 0.020 < 0.030	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
12/06/2022	< 0.030	< 0.040	< 0.030	< 0.030	< 0.030	< 0.030		
12/13/2022	< 0.020	< 0.020	< 0.010	< 0.020	< 0.020	< 0.020		
12/27/2022	< 0.030	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020		
ILILIILULL	- 0.000	- 0.020	- 0.000	- 0.000	- 0.000	- 0.000		

⁽²⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 3 ⁽³⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 4

⁽⁵⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 6

 Plant: Turkey Point Nuclear Units 3 & 4
 Year: 2022

 Annual Radiological Environmental Operating Report

 Page 35 of 56

Attachment 2

Page 4 of 16

Ana	Ia Iysis: Gamma D	adiation– Indica	Units: µR/hr		
Station	1 st Qtr 2022	2 nd Qtr 2022	3 rd Qtr 2022	4 th Qtr 2022	Annual Mean 2022
N-2	4.6	4.3	4.0	3.9	4.2
N-7	4.1	3.5	4.4	3.4	3.9
N-10	4.5	3.9	4.3	3.7	4.1
NNW-2	4.2	3.8	3.9	3.5	3.9
NNW-10	4.3	3.8	3.7	3.7	3.9
NW-1	4.7	4.2	3.7	3.7	4.1
NW-5	4.0	3.3	4.1	3.9	3.8
NW-10 ⁽¹⁾	5.1	4.7	4.2	3.4	4.4
WNW-2	4.3	3.9	3.6	3.8	3.9
WNW-10	4.7	4.3	3.5	3.5	4.0
W-1	4.6	3.8	4.1	4.2	4.2
W-5	4.3	3.8	4.5	3.4	4.0
W-9	3.9	3.5	3.9	3.5	3.7
WSW-8	4.0	3.6	4.0	3.9	3.9
SW-1	4.3	4.0	4.2	4.0	4.1
SW-8	3.1	3.1	4.4	3.9	3.6
SSW-5	3.6	3.2	4.1	3.7	3.6
SSW-10	3.7	3.6	3.8	3.7	3.7
S-5	3.2	3.2	3.9	3.1	3.4
S-10	4.2	3.7	3.2	3.4	3.6
SSE-1	3.5	3.0	3.7	3.7	3.5
SSE-10	3.5	3.3	3.9	2.8	3.4

Monitoring Results Tables

⁽¹⁾ Indicator station with highest annual mean.

Analysis: Gamma Dose			Units: μR/hr					
Station	1 st Qtr 2022	2 nd Qtr 2022	3 rd Qtr 2022	4 th Qtr 2022	Annual Mean 2022			
NNE-22	4.4	4.2	3.1	3.1	3.7			

Table 12: Direct Radiation – Control

		PI	ant: Turk	ey Point Nuclear Unit					ear: 2022	Page 3	6 of 56
	A.(. 1	1.0		Annual Radiological	Environ	mental C	perating	Report		6.4.0	
	Attachm	ent 2		Manita	wine Dee	ulta Tabla	-		Page 5	Of 16	
				Table 13: Surfac	-	ults Table		2			
		Analysis	Gamma I		e water -	- 111111111	anu Gamm	a Units: p	Ci/l		
Location	End Date	H-3	K-40		nd Date	H-3	K-40	Locati		H-3	K-40
		3,000		REQUIRED		3,000			IRED LLD ->	3,000	
T42 (Indicator)	01/20/2022	< 137	193	T67 (Control) 01/	/19/2022	< 137	269	T81 (Indicat	or) 01/20/2022	< 133	339
T42 (Indicator)	02/15/2022	84	224	(Control)	/14/2022	< 131	282	T81 (Indicat	or) 02/15/2022	< 131	237
T42 (Indicator)	03/08/2022	< 135	218	(Control)	/07/2022	< 135	171	T81 (Indicat	or) 03/08/2022	< 135	252
T42 (Indicator)	04/05/2022	< 132	304	(Control)	/04/2022	< 132	248	T81 (Indicat	or) 04/05/2022	< 132	253
T42 (Indicator)	05/03/2022	< 139	364	T67 (Control) 05/	/02/2022	< 134	298	T81 (Indicat	or) 05/03/2022	< 139	386
T42 (Indicator)	06/06/2022	< 132	260	(Control)	/06/2022	< 132	163	T81 (Indicat	or) 06/06/2022	< 132	309
T42 (Indicator)	07/05/2022	< 135	243	T67 (Control) 07/	/06/2022	< 135	127	T81 (Indicat	or) 07/05/2022	< 135	347
T42 (Indicator)	08/02/2022	< 137	398	(Control)	/03/2022	< 137	194	T81 (Indicat	or) 08/02/2022	< 137	334
T42 (Indicator)	09/07/2022	< 136	378	T67	/06/2022	< 133	170	T81 (Indicat	09/07/2022	< 136	342
T42 (Indicator)	10/04/2022	< 131	222	T67 (Control) 10/	/04/2022	< 131	216	T81 (Indicat	or) 10/04/2022	< 131	274
T42 (Indicator)	11/01/2022	< 129	292	T67	/31/2022	< 129	149	T81 (Indicat	11/01/2022	< 129	296
T42 (Indicator)	12/13/2022	< 134	251	T67	/14/2022	< 134	268	T81 (Indicat	or) 12/13/2022	< 134	284

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 37 of 56
Appual Padiological Environmental Opera	ting Poport	

Annual Radiological Environmental Operating Report

Attachment 2

Page 6 of 16

Monitoring Results Tables

 Table 14: Shoreline Sediment - Gamma

	Analysis: Ga	mma Isotopi	с		Units: pCi/kg (dry)						
Location Collection Date		Be-7 K-40		Cs-137	Pb-210	Ra-226	Th-232	U-235	U-238		
REQUIRED LLD ->				<u>180</u>							
T42 (Indicator)	01/20/2022	80	< 140	< 9	< 322	425	< 39	27	132		
T67 (Control)	01/20/2022	116	102	< 10	< 533	449	< 42	44	563		
T81 (Indicator)	01/20/2022	< 67	122	< 8	< 382	386	< 64	24	133		
T42 (Indicator)	07/05/2022	< 121	164	< 10	< 1050	332	< 46	< 23	211		
T67 (Control)	07/06/2022	< 93	662	< 9	< 838	< 41	< 63	< 18	< 201		
T81 (Indicator)	07/05/2022	< 140	224	< 11	< 1060	487	< 52	75	238		

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 38 of 56Annual Radiological Environmental Operating Report

Attachment 2

Page 7 of 16

Monitoring Results Tables

Analysis:	Gamma Isotop	ic	Units: pCi/kg (wet)					
Location	Collection Date	Sample Type	K-40	Ra-226	Ra-228			
RE	QUIRED LLD 🗲							
T67 (Control)	05/04/2022	Blue Crab	693	< 253	< 69			
T81 (Indicator)	05/03/2022	Blue Crab	1460	< 367	< 75			
T67 (Control)	11/01/2022	Blue Crab	1320	< 567	< 1320			
T81 (Indicator)	11/02/2022	Blue Crab	1640	< 464	< 1640			

Table 15: Crustacea - Gamma

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 39 of 56Annual Radiological Environmental Operating Report

Attachment 2

Page 8 of 16

Monitoring Results Tables

Analysis	: Gamma Isotop	ic	Units: pCi/kg (wet)				
Location	Collection Date	Sample Type		Ra-226	Ra-228		
<u>RE</u>	QUIRED LLD 🗲						
T67 (Control)	04/06/2022	Mixed Species	2570	< 23	< 475		
T81 (Indicator)	dicator) 04/05/2022		2650	< 343	< 72		
T67 (Control)	07/06/2022	Mixed Species	2230	< 337	< 57		
T81 (Indicator)	07/05/2022	Mixed Species	2150	< 490	< 88		

Table 16: Fish - Gamma

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 40 of 56Annual Radiological Environmental Operating Report

Attachment 2

Page 9 of 16

Monitoring Results Tables Table 17⁻ Broad Leaf Vegetation - Gamma

	Table 17: Broad Leaf Vegetation - Gamma Analysis: Gamma Isotopic Units: pCi/kg (wet)											
	Analysis: Gam	ma Isotopic			Unit	s: pCi/kg (wet)					
Location	Collection Date	Sample Type	Be-7	K-40	Cs-137	Pb-210	Pb-212	Ra-226				
		REQUIRED LLD 🗲			<u>80</u>							
T40 (Indicator)	01/19/2022	Brazilian Pepper	1210	3640	22	< 110	< 18	< 214				
T40 (Indicator)	02/14/2022	Brazilian Pepper	3060	4220	117	84	< 24	< 270				
T40 (Indicator)	03/07/2022	Brazilian Pepper	2450	5260	46	125	< 19	< 227				
T40 (Indicator)	04/04/2022	Brazilian Pepper	2150	2790	80	< 829	< 26	< 337				
T40 (Indicator)	05/03/2022	Brazilian Pepper	1660	2440	10	89	< 16	< 208				
T40 (Indicator)	06/06/2022	Brazilian Pepper	925	4650	< 13	< 95	< 23	< 257				
T40 (Indicator)	07/06/2022	Brazilian Pepper	1240	3940	46	< 715	< 22	< 258				
T40 (Indicator)	08/03/2022	Brazilian Pepper	1840	3870	14	< 657	< 22	< 264				
T40 (Indicator)	09/07/2022	Brazilian Pepper	1490	3890	43	< 1050	< 36	< 438				
T40 (Indicator)	10/04/2022	Brazilian Pepper	1750	5810	< 12	< 95	< 22	< 239				
T40 (Indicator)	11/01/2022	Brazilian Pepper	1810	4540	39	< 667	< 24	< 268				
T40 (Indicator)	12/13/2022	Brazilian Pepper	1310	6100	13	< 102	< 24	< 274				
T41(Indicator)	01/18/2022	Brazilian Pepper	825	4660	< 13	< 267	< 21	< 247				
T41(Indicator)	02/14/2022	Brazilian Pepper	2660	6350	28	< 137	< 25	< 291				
T41(Indicator)	03/07/2022	Brazilian Pepper	1690	3160	< 11	75	< 20	< 229				
T41(Indicator)	04/04/2022	Brazilian Pepper	1150	2070	< 11	< 99	< 19	< 212				
T41(Indicator)	05/03/2022	Brazilian Pepper	1500	5900	< 16	< 130	< 23	< 268				
T41(Indicator)	06/06/2022	Brazilian Pepper	1420	2830	< 11	< 886	< 24	< 370				
T41(Indicator)	07/06/2022	Brazilian Pepper	579	3390	< 9	< 624	< 21	< 244				
T41(Indicator)	08/02/2022	Brazilian Pepper	1170	4050	< 11	463	< 20	< 271				
T41(Indicator)	09/07/2022	Brazilian Pepper	723	3780	< 16	< 849	< 21	< 366				
T41(Indicator)	10/04/2022	Brazilian Pepper	1880	4200	45	1610	< 36	295				
T41(Indicator)	11/01/2022	Brazilian Pepper	1230	4060	20	< 81	< 18	< 227				
T41(Indicator)	12/13/2022	Brazilian Pepper	1550	5590	< 19	< 1100	< 35	< 431				
T67 (Control)	01/19/2022	Brazilian Pepper	1060	5090	< 9	47	< 15	< 181				
T67 (Control)	02/14/2022	Brazilian Pepper	1140	5340	< 11	< 303	< 21	< 238				
T67 (Control)	03/07/2022	Brazilian Pepper	535	5270	< 16	544	< 29	< 350				
T67 (Control)	04/04/2022	Brazilian Pepper	1830	4920	< 14	< 1230	< 27	< 300				
T67 (Control)	05/02/2022	Brazilian Pepper	1300	5680	< 16	< 240	< 30	< 348				
T67 (Control)	06/06/2022	Brazilian Pepper	1290	4670	< 13	562	< 27	< 329				
T67 (Control)	07/06/2022	Brazilian Pepper	641	3760	< 9	< 67	< 15	< 187				
T67 (Control)	08/03/2022	Brazilian Pepper	790	3780	< 9	< 587	< 20	219				
T67 (Control)	09/06/2022	Brazilian Pepper	1100	4660	< 7	< 86	< 19	< 234				
T67 (Control)	10/04/2022	Brazilian Pepper	1270	4600	< 13	< 95	< 22	< 238				
T67 (Control)	10/31/2022	Brazilian Pepper	1410	4580	< 17	< 1190	< 32	< 382				
T67 (Control)	12/14/2022	Brazilian Pepper	954	4450	< 14	< 685	< 22	< 254				

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Annual Radiological Environmental Operating Report Page 41 of 56

Attachment 2

Page 10 of 16

٨٣٥	Table 18: Iysis: Gamma D	Supplemental D	irect Radiation-		
Station	1 st Qtr 2022	2 nd Qtr 2022	3 rd Qtr 2022	Units: μR/hr 4 th Qtr 2022	Annual Mean 2022
NNW-6	4.0	3.7	3.7	3.7	3.8
NW-7	4.8	4.1	3.5	3.8	4.1
NW-8 ⁽¹⁾	4.9	(2)	4.1	3.5	4.2
WNW-3	4.2	3.9	4.0	3.5	3.9
WNW-6	4.1	4.0	4.2	3.9	4.0
W-8	4.4	3.9	3.9	3.7	4.0
ENE-1	3.3	(3)	3.2	3.0	3.1
T72	4.0	3.6	3.7	3.4	3.7
PTN-1	4.0	3.8	4.0	3.5	3.8

⁽¹⁾ Indicator station with highest annual mean.
 ⁽²⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 2

⁽³⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 1

Plant: Turkey Point Nuclear Units 3 & 4 Page 42 of 56 Year: 2022 Annual Radiological Environmental Operating Report

Attachment 2

Page 11 of 16

	Monitoring Results Ta Fable 19: Supplemental Air Particu	
	alysis: Gross Beta	Units: pCi/m ³
End Date	T52 (Indicator)	T56 (Indicator)
LLD 🗲	0.01	0.01
01/06/2022	0.013	0.016
01/12/2022	0.014	0.014
01/19/2022	0.016	0.018
01/27/2022	0.015	0.014
02/02/2022	0.021	0.017
02/09/2022	0.011	0.012
02/15/2022	0.017	0.018
02/24/2022	0.013	0.012
03/02/2022	0.009	0.010
03/07/2022	0.012	0.012
03/16/2022	0.007	0.006
03/23/2022	0.011	0.013
03/30/2022	0.019	0.019
04/05/2022	0.014	0.011
04/13/2022	0.014	0.019
04/19/2022	0.008	0.008
04/27/2022	0.014	0.015
05/02/2022	0.009	0.010
05/11/2022	0.014	0.014
05/17/2022	0.010	0.012
05/24/2022	0.021	0.022
05/31/2022	0.021	0.023
06/06/2022	< 0.001	0.005
06/14/2022	0.012	0.011
06/21/2023	0.016	0.011
06/27/2023	0.015	0.018
07/04/2022	0.007	0.008
07/12/2022	0.011	0.009
07/19/2022 07/26/2022	0.011 0.012	0.012 0.013
08/01/2022	0.012	0.013
08/09/2022	(1)	(1)
08/16/2022	0.017	0.015
08/23/2022	0.009	0.013
09/06/2022	0.007	0.002
09/14/2022	0.006	0.005
09/20/2022	0.009	0.008
09/26/2022	0.021	0.015
09/30/2022	(2)	(2)
10/04/2022	0.005	0.005
10/11/2022	0.011	0.008
10/19/2022	0.009	0.011
10/25/2022	0.014	0.019
10/31/2022	0.011	0.011
11/09/2022	0.012	0.012
11/15/2022	0.009	0.010
11/21/2022	0.009	0.010
11/30/2022	0.007	0.011
12/06/2022	0.017	0.013
12/13/2022	0.017	0.015
12/21/2022	0.012	0.020

0.023 ⁽¹⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 5

0.012

0.020

0.016

12/21/2022

12/27/2022

⁽²⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 6

Plan	t: Turkey Point Nuc	lear Units 3 8	& 4	Year: 2022	2 Pa	ge 43 of 56					
	Annual	Radiological	Environmental (Operating Repo	rt						
Attach	ment 2				Page 12 of	16					
		Monito	ring Results Tabl	es							
	Table 20:	Supplemental	Air Particulate C	omposite - Gamr	na						
Analysis: Gamma Isotopic Units: pCi/m ³											
Location	Collection Date	Be-7	K-40	Cs-134	Cs-137	Pb-210					
	REQUIRED LLD ->			<u>0.05</u>	<u>0.06</u>						
T52 (Indicator)	03/30/2022	0.1380	< 0.0146	< 0.0010	< 0.0010	< 0.0153					
T56 (Indicator)	03/30/2022	0.1230	< 0.0149	< 0.0009	< 0.0007	< 0.0333					
T52 (Indicator)	06/14/2022	0.1240	< 0.0169	< 0.0011	< 0.0010	< 0.0329					
T56 (Indicator)	06/14/2022	0.1290	< 0.0079	< 0.0014	< 0.0010	< 0.0114					
T52 (Indicator)	09/26/2022	0.0633	< 0.0153	< 0.0013	< 0.0011	< 0.0109					
T56 (Indicator)	09/26/2022	0.0633	< 0.0153	< 0.0013	< 0.0011	< 0.0109					
T52 (Indicator)	12/28/2022	0.0960	< 0.0119	< 0.0010	< 0.0007	< 0.0315					
T56 (Indicator)	12/28/2022	0.1250	< 0.0189	< 0.0012	< 0.0008	< 0.0086					

Plant: Turkey Point Nuclear Units 3 & 4 Year: 2022 Annual Radiological Environmental Operating Report Page 44 of 56

Attachment 2

Page 13 of 16

	Table 21: Supplemental Air Ca	
A	nalysis: lodine-131	Units: pCi/m ³
End Date	T52 (Indicator)	T56 (Indicator)
LLD 🗲	0.07	0.07
01/06/2022	< 0.010	< 0.010
01/12/2022	< 0.030	< 0.030
01/19/2022	< 0.020	< 0.020
01/27/2022	< 0.010	< 0.010
02/02/2022	< 0.020	< 0.020
02/09/2022	< 0.020	< 0.020
02/15/2022	< 0.030	< 0.030
02/24/2022	< 0.020	< 0.020
03/02/2022	< 0.020	< 0.020
03/07/2022	< 0.030	< 0.030
03/16/2022	< 0.020	< 0.020
03/23/2022	< 0.020	< 0.020
03/30/2022	< 0.020	< 0.020
04/05/2022	< 0.030	< 0.020
04/13/2022	< 0.020	< 0.020
04/19/2022	< 0.030	< 0.030
04/27/2022	< 0.020	< 0.020
05/02/2022	< 0.010	< 0.010
05/11/2022	< 0.020	< 0.020
05/17/2022	< 0.030	< 0.030
05/24/2022	< 0.030	< 0.030
05/31/2022	< 0.020	< 0.020
06/06/2022	< 0.030	< 0.020
06/14/2022	< 0.020	< 0.020
06/21/2022	< 0.020	< 0.020
06/27/2022	< 0.030	< 0.030
07/04/2022	< 0.020	< 0.020
07/12/2022	< 0.030	< 0.020
07/19/2022	< 0.030	< 0.030
07/26/2022	< 0.020	< 0.020
08/01/2022	< 0.030	< 0.030
08/09/2022	(1)	(1)
08/16/2022	< 0.020	< 0.020
08/23/2022	< 0.020	< 0.020
09/06/2022	< 0.010	< 0.010
09/14/2022	< 0.020	< 0.020
09/20/2022	< 0.020	< 0.020
09/26/2022	< 0.030 (2)	< 0.030
09/30/2022	.,	.,
10/04/2022	< 0.010	< 0.010
10/11/2022	< 0.030	< 0.030
10/19/2022	< 0.020	< 0.020
10/25/2022	< 0.030	< 0.030
10/31/2022	< 0.030	< 0.030
11/09/2022	< 0.020	< 0.020
11/15/2022	< 0.030	< 0.030 < 0.030
11/21/2022 11/30/2022	< 0.030 < 0.020	< 0.030
12/06/2022	< 0.040	< 0.030
12/13/2022 12/21/2022	< 0.020 < 0.020	< 0.010 < 0.020
12/27/2022	< 0.030	< 0.030

Monitoring Results Tables

(1) See Attachment 1, Table 7, Samples Deviations Table, Comment 5

⁽²⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 6

Plant: Turkey Point Nuclear Units 3 & 4 Year: 2022 Page 45 of 56 Annual Radiological Environmental Operating Report Attachment 2 Page 14 of 16

Monitoring Results Tables

Table 22: Supplemental Surface Water – Tritium and Gamma

		An	alysis:	Gar	mma Isotop	ic			Units: pCi/L								
Location	End Date	H-3	K-40		Location	End Date	H-3	K-40	Location	End Date	H-3	K-40		Location	End Date	H-3	K-40
REQUIRE	D LLD 🗲	<u>3,000</u>			REQUIRE	D LLD 🗲	<u>3,000</u>		REQUIRE	D LLD 🗲	<u>3,000</u>			REQUIRE	D LLD 🗲	<u>3,000</u>	
T08 (Indicator)	01/20/2022	6945	298		T75 (Indicator)	01/18/2022	< 133	< 42	T84 (Indicator)	01/19/2022	7044	270		T97 (Indicator)	01/20/2022	7028	283
T08 (Indicator)	02/15/2022	5655	248		T75 (Indicator)	02/14/2022	< 131	< 68	T84 (Indicator)	02/15/2022	5560	283		T97 (Indicator)	02/15/2022	5611	311
T08 (Indicator)	03/08/2022	9063	275		T75 (Indicator)	03/07/2022	< 135	< 66	T84 (Indicator)	03/07/2022	7944	328		T97 (Indicator)	03/08/2022	7876	305
T08 (Indicator)	04/05/2022	11098	353		T75 (Indicator)	04/04/2022	< 133	< 76	T84 (Indicator)	04/04/2022	11679	390		T97 (Indicator)	04/05/2022	11094	293
T08 (Indicator)	05/03/2022	8530	416		T75 (Indicator)	05/03/2022	< 140	< 42	T84 (Indicator)	05/03/2022	8407	370		T97 (Indicator)	05/03/2022	8199	352
T08 (Indicator)	06/06/2022	3310	276		T75 (Indicator)	06/06/2022	< 133	< 82	T84 (Indicator)	06/06/2022	3142	317		T97 (Indicator)	06/06/2022	3219	233
T08 (Indicator)	07/05/2022	2322	344		T75 (Indicator)	07/06/2022	< 135	< 64	T84 (Indicator)	07/05/2022	2214	363		T97 (Indicator)	07/06/2022	2172	256
T08 (Indicator)	08/02/2022	1628	400		T75 (Indicator)	08/02/2022	< 137	< 73	T84 (Indicator)	08/02/2022	1570	298		T97 (Indicator)	08/02/2022	1570	272
T08 (Indicator)	09/07/2022	1049	394		T75 (Indicator)	09/07/2022	< 136	< 41	T84 (Indicator)	09/07/2022	1084	408		T97 (Indicator)	09/07/2022	2322	344
T08 (Indicator)	10/04/2022	1137	242		T75 (Indicator)	10/04/2022	< 131	< 52	T84 (Indicator)	10/04/2022	1140	362		T97 (Indicator)	10/04/2022	1278	276
T08 (Indicator)	11/01/2022	1236	357		T75 (Indicator)	11/01/2022	< 129	< 73	T84 (Indicator)	11/01/2022	1128	300		T97 (Indicator)	11/01/2022	1090	240
T08 (Indicator)	12/13/2022	3234	336		T75 (Indicator)	12/13/2022	< 134	41	T84 (Indicator)	12/13/2022	3084	312		T97 (Indicator)	12/13/2022	2971	320

	Plant: Turkey Poir	nt Nuclear	Units 3 &	4		Year:	2022	Page 4	6 of 56		
	Ann	ual Radio	logical Env	rironmenta	al Operating	g Report					
Attach	ment 2							Page 15 o	f 16		
			Monitoring	Results Ta	ables						
	Та	able 23: Suj	pplemental	Shoreline S	Sediment - G	amma					
	Analysis: Gamma	Isotopic				Uni	ts: pCi/kg (d	lry)			
Location	LocationCollection DateBe-7K-40Cs-137Pb-210Ra-226Th-232										
	REQUIRED LLD 🗲			<u>180</u>							
T01 (Indicator)	01/20/2022	< 62	< 153	< 9	343	634	< 43	40	207		
T02 (Indicator)	03/08/2022	< 111	385	< 14	307	1060	< 48	67	183		
T03 (Indicator)	03/08/2022	< 204	1410	13	2060	2210	< 123	139	< 383		
T04 (Indicator)	01/20/2022	106	198	< 10	593	731	< 41	46	311		
T07 (Indicator)	03/08/2022	< 116	815	29	< 704	< 494	< 58	58	< 183		
T08 (Indicator)	03/08/2022	< 155	< 185	< 15	< 1670	1370	< 73	86	80		
T10 (Indicator)	03/08/2022	< 176	700	< 17	< 1660	< 621	< 92	< 39	< 308		
T84* (Indicator)	01/20/2022	142	235	< 13	817	1190	< 53	75	405		
T85* (Indicator)	01/20/2022	< 111	562	< 14	575	858	< 95	54	198		
T84* (Indicator)	07/05/2022	383	931	< 33	< 32	< 14	15	1630	438		
T85* (Indicator)	07/06/2022	< 198	560	< 40	< 43	< 18	< 21	< 667	106		

* Note that site T48 is the same location as site T05, and site T85 is the same location as site T06.

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 47 of 56Annual Radiological Environmental Operating Report

Attachment 2

Page 16 of 16

Monitoring Results Tables

 Table 24: Supplemental Food Crops - Gamma

	Analysis: Ga	Units: pCi/kg (wet)				
Location	Collection Date	Be-7	K-40	Cs-137	Ra-226	
		REQUIRED LLD 🗲			<u>80</u>	
T43 (Indicator)	01/20/2022	Corn & Green Beans	< 76	2510	< 11	< 206
T44 (Indicator)	02/14/2022	Corn & Green Beans	< 59	2210	< 8	< 144
T45 (Indicator)	03/07/2022	Corn & Green Beans	< 110	2410	< 13	< 401

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 48 of 56		
Annual Radiological Environmental Operating Report				

Attachment 3

Interlaboratory Comparison Program Results

Page 1 of 3

1.0 Summary

The Interlaboratory Comparison Program consists of participating in the DOE Mixed Analyte Performance Evaluation Program (MAPEP).

This program provides similar testing (matrices, nuclides, and levels) as the former EPA Interlaboratory Comparison Program and is referred to as the Mixed Analyte Performance Evaluation Program (MAPEP).

The samples are analyzed using the methods applicable to the REMP (gamma spectroscopy, Gross Beta, and Tritium for water).

From the MAPEP handbook:

Acceptance criteria were developed from a review of precision and accuracy data compiled by other performance evaluation programs (PEPs), the analytical methods literature, from several MAPEP pilot studies, and from what is considered reasonable, acceptable, and achievable for routine analyses among the more experienced laboratories.

The State laboratory participated in MAPEP 46 and 47. These satisfied the requirement of Control 5.3 of the ODCM for the Interlaboratory Comparison Program.

Plant: Turkey Point Nuclear Units 3 & 4

Year: 2022

Annual Radiological Environmental Operating Report

Attachment 3 Page 2 of								
		-	-	n Program Resul				
	DE's Mixed Ana	alyte Perforr	nance Evalı Ref.	•	MAPEP) 46 RESULTS Acceptance			
Program status	Radionuclide	Result	Value	Flag (Evaluation)	Range			
Matrix: RdF Air Filter Bq/filter								
Required	MN54	0.004		А	False Positive Test			
Required	CO57	0.018		А	False Positive Test			
Required	CO60	0.728	0.72	А	0.50 - 0.94			
	ZN65	-0.005		А	False Positive Test			
Required	CS134	0.852	0.93	А	0.65 - 1.21			
Required	CS137	0.733	0.726	А	0.508 - 0.944			
•	Air Filter Bq/filt							
Required	Gross Beta	0.645	0.681	А	0.341 – 1.022			
Required	Gross Alpha	0.916	1.20	А	0.36 - 2.04			
Matrix: Ma	aS Soil Bq/kg							
Required	K40	568.25	596	А	417 - 775			
	MN54	1104.17	1140	А	798-1482			
	CO57	1217.50	1400	А	980 - 1820			
	CO60	410.83	443	А	310 - 576			
	ZN65	0.86		А	False Positive Test			
	CS134	886.32	890	А	623-1157			
Required	CS137	335.00	365	А	256 - 475			
	aW Water Bq/L							
Required	H3	322.92	300	А	210-390			
	MN54	18.347	18.9	А	13.2 – 24.6			
	CO57	34.068	36.0	А	25.2 - 46.8			
Required	CO60	8.778	9.3	А	6.5-12.1			
	ZN65	26.704	26.2	А	18.3 – 34.1			
Required	CS134	0.047		А	False Positive Test			
Required	CS137	7.469	7.64	А	5.35 – 9.93			
	SR90	13.6676	12.9	А	9.0 – 16.8			
Matrix: Rd	V Vegetation, Bo	q/sample						
	MN54	2.895	2.59	A	1.81 – 3.37			
	CO57	6.153	5.09	W	3.56 - 6.62			
Required	CO60	0.021		А	False Positive Test			
	ZN65	1.718	1.47	А	1.03 – 1.91			
	CS134	8.082	7.61	А	5.33 – 9.89			
Required	CS137	1.733	1.52	А	1.06 – 1.98			

Evaluation: A = Acceptable, W = Acceptable with Warning, N = Not Acceptable, NR = Not Reported

A false positive test with an "A" designation flag identifies the result as less than the detectable activity, since MAPEP does not report zero values. Sensitivity Evaluation has no acceptance range but an identified value at low activity.

Plant: Turkey Point Nuclear Units 3 & 4

Page 50 of 56

Annual Radiological Environmental Operating Report

Year: 2022

Attachment 3 Page 3					
		-	-	n Program Resu	
Table 26: DC Program	DE's Mixed An	alyte Perfori	mance Eval Ref.	u ation Program (Flag	MAPEP) 47 RESULTS Acceptance
status	Radionuclide	Result	Value	(Evaluation)	Range
Matrix: Ro	dF Air Filter Bq/	filter			
Required	MN54	2.063	1.88	А	1.32 – 2.44
Required	CO57	3.268	3.32	А	2.32 - 4.32
Required	CO60	2.06	1.99	А	1.39 - 2.59
	ZN65	1.847	1.58	А	1.11 – 2.05
Required	CS134	0.02		А	False Positive Test
Required	CS137	1.622	1.53	А	1.07 - 1.99
Matrix: Gr	F Air Filter Bq/f	ilter			
Required	Gross Beta	1.213	1.31	А	0.66 – 1.97
Required	Gross Alpha	1.026	0.90	А	0.27 - 1.53
Matrix: Ma	aS Soil Bq/kg				
Required	K40	523.96	537	А	376 - 698
	MN54	831.75	841	А	589 - 1093
	CO57	680.83	786	А	550 - 1022
	CO60	-0.14		А	False Positive Test
	ZN65	1159.58	1140	А	798 - 1482
	CS134	629.95	627	А	439 - 815
Required	CS137	0.86		А	False Positive Test
-	aW Water Bq/I	_			
Required	H3	400.44	395	А	277 - 514
	MN54	0.175		А	False Positive Test
	CO57	28.828	30.0	А	21.0 - 39.0
Required	CO60	16.385	17.0	А	11.9 – 22.1
	ZN65	11.827	11.3	А	7.9 – 14.7
Required	CS134	16.037	17.1	А	12.0 – 22.2
Required	CS137	17.21	16.8	А	11.8 – 21.8
	SR90	8.06	7.73	А	5.41 - 10.05
Matrix: Rd	V Vegetation, E		-		
	MN54	2.565	2.43	А	1.70 – 3.16
	CO57	0.009	-	A	False Positive Test
Required	CO60	4.751	4.62	A	3.23 – 6.01
	ZN65	8.035	7.49	A	5.24 - 9.74
	CS134	-0.02	7.10	A	False Positive Test
Required	CS134	1.224	1.083	A	0.758 – 1.408
				Not Acceptable NR =	

Evaluation: A = Acceptable, W = Acceptable with Warning, N = Not Acceptable, NR = Not Reported

A false positive test with an "A" designation flag identifies the result as less than the detectable activity, since MAPEP does not report zero values. Sensitivity Evaluation has no acceptance range but an identified value at low activity.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2022	Page 51 of 56			
Appual Padiological Environmental Operating Pepert					

Annual Radiological Environmental Operating Report

Attachment 4

Page 1 of 4

Industry Initiative Ground Water Protection Program 2022

1.0 Description of Program

Turkey Point Nuclear maintains a sampling and analysis program to meet procedural requirements. The procedures that govern the performance are EV-AA-100-1001, *Fleet Ground Water Protection Program Implementing Guideline* and 0-ADM-654, *Ground Water Protection Program*.

The sampling frequency is quarterly; more often if conditions warrant.

Sample assay is performed by a private contractor GEL labs.

2.0 Discussion

The Turkey Point Nuclear site is surrounded on three sides by the closed cooling canal system. This canal system, in addition to being the source of tertiary cooling, is the body of water receiving permitted liquid radiological waste the canal system tritium level averages was 5,005 pCi/L in 2022 with a max concentration of 11,679 pCi/L. This supports the expectation to see tritium in subsurface water collected either on-site or off-site close to the (within the Owner Controlled Area) cooling canal system. Twenty-eight (28) wells were involved in the 2022 monitoring program; some locations have multiple (two or three) depths.

Samples are analyzed for Tritium & Gamma emitters. As conditions warrant, analysis included Fe-55, Ni-63, Sr-89/90 and alpha (all were < LLD).

3.0 Results

The tritium results for the groundwater wells were from <MDA to 3,980 pCi/L. All results were less than the limits of the Offsite Dose Calculation Manual, Table 5.1-2, Reporting Levels for Radioactivity Concentrations in Environmental Samples. Storm drain outfalls occasionally are below the tidal mark of the canal and will have ingress of canal water into the storm drain. The higher levels of tritium in the storm drain section are due to the canal water ingress into the storm drain.

Tabular results follow:

Plant: Turkey Point Nuclear Units 3 & 4 Year: 2022 Page 52 of 56 Annual Radiological Environmental Operating Report Page 2 of 4

Attachment 4

	Table 27:	Ground Water – Tr	ritium		
Analysis: Tr	itium	Units: pCi/L			
Location	First Quarter 2022 H-3	Second Quarter 2022 H-3	Third Quarter 2022 H-3	Fourth Quarter 2022 H-3	
REQUIRED LLD 🗲	<u>3,000</u>	<u>3,000</u>	<u>3,000</u>	<u>3,000</u>	
PTPED-1	299	199	281	409	
CD-1	459	0.282	262	559	
P-94-2	408		347		
P-94-4	867	595	356	843	
STP-1	65		92.7		
PTN-MW-1s	32		-38.3		
PTN-MW-1i	277		343		
PTN-MW-1d	1050		1330		
PTN-MW-2s	140		-55		
PTN-MW-3s	47		170		
PTN-MW-4s	96	-7.31	95.3	128	
PTN-MW-4i	3510	-7.22	3690	3980	
PTN-MW-4d	22	33.3	-29.1	86	
PTN-MW-5s	86	-12.1	55.2	108	
PTN-MW-5i	97	23.4	-38.6	97	
PTN-MW-5d	1050	1170	1120	1560	
PTN-MW-6s	51		65.4	-10.5	
PTN-MW-6SR				127/-46.4 ⁽¹⁾	
PTN-MW-6d	1430		1120	1570	
PTN-MW-6DR				748/223 ⁽¹⁾	
PTN-MW-7s	1340	969	1540	2160	
PTN-MW-7i	3240	3100	83.3	3560	
PTN-MW-7d	159	3.51	103	162	
PTN-MW-8s	2750	427	3390	2520	
PTN-MW-9s	1120	885	784	843	
PTN-MW-10s	-35		0.0478		
PTN-MW-10i	19		16.3		
PTN-MW-10d	-39		-0.0245		
PTN-MW-11s	151	30.3	139	222	
PTN-MW-12s	1120	789	731	1220	
NE StrmDrain	431	5700	2550	2370	
SE StrmDrain	647	(3)	4940	(2)	
W StrmDrain	6150	(3)	1390	(2)	
CRF StrmDrain	Dry	Dry	Dry	Dry	

Monitoring Results Tables

⁽¹⁾ Replacement wells 6DR & 6SR were sampled twice in Qtr. 4.

⁽²⁾ Storm Drain submerged underwater at time of collection.

⁽³⁾ Sample inadvertently discarded prior to shipping off for analysis.

Plant: Turkey Point Nuclear Units 3 & 4Year: 2022Page 53 of 56Annual Radiological Environmental Operating Report

Attachment 4


Page 3 of 4

Industry Initiative Ground Water Protection Program 2022

D. List of wells and their locations

Well Name	Location		
PTN-MW-1s PTN-MW-1i PTN-MW-1d	Northeast of Switch Yard, South of entrance road to Fossil Plant		
PTN-MW-2s	South Switch Yard by parking lot		
PTN-MW-3s	Northeast of new Issues Warehouse		
PTN-MW-4s PTN-MW-4i PTN-MW-4d	SW corner of parking lot South of Training Bldg.		
PTN-MW-5s PTN-MW-5i PTN-MW-5d	SW of CRF, by canal		
PTN-MW-6s PTN-MW-6SR PTN-MW-6d PTN-MW-6DR	NE of site in the berm for fossil oil tanks		
PTN-MW-7s PTN-MW-7i PTN-MW-7d	NE of RCA, by Neutralization Tank		
PTN-MW-8s	Near U3 RWST		
PTN-MW-9s	Near U4 RWST		
PTN-MW-10s PTN-MW-10i PTN-MW-10d	SE of Radwaste Bldg. by S/G Bldg.		
PTN-MW-11s	South of truck entrance to Rad Waste Bldg.		
PTN-MW-12s	West of Condenser Polisher road		
STP-1	West of Maintenance Bldg. on corner or road into parking lot		
P-94-4	East of Dressout Building, under delay fence		
P-94-2	By Neutralization Basin, East of the RCA		
CD-1	By Neutralization Basin, East of the RCA		
PTPED-1	By Neutralization Basin, East of the RCA		

Note: s, i and d refer to well depth: shallow - 20 ft., intermediate - 40 ft. and deep - 60 ft Maps depicting the well locations follow.



Attachment 4

Page 4 of 4

Industry Initiative Ground Water Protection Program 2022

4 PTN-MW-6S/D - 6 PTN-SG-1 PTN-SG-1A ា PTN-MW-1S/I/D E-W BASELINE PTN-SG **≜**B' В -MW-85 NHMW-2S PTN-MW-12S 0 PTN-SG-2 PTN-MW-11S TN-MW-10S/I/D PTN-MW-3S 54.1 ι, PTN-MW-4S/I/D PTN-MW-5S/I/D A PTN-SG-4 LEGEND A ACTIVE MONITORING WELL LOCATION LINE OF CROSS-SECTION ABANDONED / DESTROYED MONITORING WELL LOCATION STORM DRAIN SYSTEM • TP-2 STORM DRAIN LOCATION PTPED-8 UNKNOWN MONITORING WELL LOCATION figure 4 PTN-SG-1 STAFF GAUGE LOCATION ۵ MONITORING WELL AND STAFF GAUGE LOCATION MAP SITE CONCEPTUAL MODEL TURKEY POINT FACILITY Florida Power & Light Co. MONITORING WELL LOCATION PTN-MW-2S

Figure 5: Onsite Tritium Monitoring Wells

11145832-01(001) ON-WA004 MAR 23, 2018

Year: 2022

Annual Radiological Environmental Operating Report

Attachment 5

Page 1 of 2

ERRATA Data 2022

Significant errors should be corrected within one year of discovery, and the correction may be submitted with the next (normally scheduled) submittal of the AREOR as follows. A brief narrative explanation of the errors should be included in, "Errata/Corrections to Previous AREORs," "Supplemental Information." The narrative should include a statement that the affected pages, in their entirety, are included as attachments to the AREOR. Additionally, the affected, corrected pages, in their entirety, should be submitted as an attachment to the AREOR. The corrected pages should reference the affected calendar year and should contain revision bars in the margins of the page to indicate the locations of the changes. If submitting corrections to multiple AREORs, make a separate attachment for each of the affected years. Other methods of correcting previous AREORs may be used provided the corrections are clearly and completely described.

Significant errors include:

- Inaccurate reporting of samples collected and analyzed.
- Inaccurate reporting of sample results.
- Omissions that impede the NRC's ability to adequately assess the information supplied by the licensee, or other errors that alter the intent of the report.

1.0 List of changes from the 2021 AREOR.

- 1. Page 30 of 55: The entries that indicated tritium reporting levels exceeded were removed. According to the ODCM this value does not exceed the reporting limit nor level.
- 2. Page 31 of 55: Comment number 13, now Comment number 8, had the incorrect AR# listed in the Evaluation/Actions box. The AR# was changed from "AR# 0422809" to "AR# 02422809".

Sample	e Deviations
--------	--------------

Comment No.	Sample Media Affected	Sample Location	Date	Problem	Evaluation / Actions
1	Air Sample	T72	01/06/21	Pump Failure	Vacuum Pump failed, estimated run time was 64 out of 191 hours. T72 vacuum pump was replaced. AR# 02399193
2	Air Sample	T72	01/20/21	Power Outage	Power outage at station T72, estimated run time was 20 out of the 150 hours. The power was restored 01/22/21 at 14:03. AR# 02399193
3	Air Sample	T72	01/25/21	Power Outage	Due to previous power outage, this week's filter ran for 74 hours. AR# 02399193
4	Air Sample	T51	05/26/21	Pump Failure	Vacuum Pump failed, estimated run time 91 hours out of 149 hours. T51 Vacuum pump was replaced. AR# 02399193
5	Air Sample	T51	06/02/21	Power Outage	Power outage at station T51, estimated run time was 124 out of the 161 hours. AR# 02399193
6	Air Sample	T72	06/09/21	Sample Missing	Air Cartridge lost somewhere between shipping it and receiving it. AR# 02399193
7	Air Sample	T58	08/18/21	Pump Failure	Vacuum Pump failed, estimated run time was 74.3 out of 120.9 hours. T58 sample pump was replaced. AR# 02411663
8	Milk	Т99	2021	Sample Unavailable	Goat milk sample was unavailable this year. The farm has not had any milking goats. AR# 02422809

Table 7: Sample Deviations Table

Annual Radiological Environmental Operating Report

Attachment 5

Page 2 of 2

ERRATA Data 2022

3. Page 52 of 55: The value listed for canal system's tritium level average of 7,126 pCi/L was corrected to 7,970 pCi/L.

2.0 Discussion

The Turkey Point Nuclear site is surrounded on three sides by the closed cooling canal system. This canal system, in addition to being the source of tertiary cooling, is the body of water receiving permitted liquid radiological waste the canal system tritium level averages was 7,970 pCi/L in 2021 with a max concentration of 13,492 pCi/L. This supports the expectation to see tritium in subsurface water collected either on-site or off-site close to the (within the Owner Controlled Area) cooling canal system. Twenty-eight (28) wells were involved in the 2021 monitoring program; some locations have multiple (two or three) depths.

Samples are analyzed for Tritium & Gamma emitters. As conditions warrant, analysis included Fe-55, Ni-63, Sr-89/90 and alpha (all were < LLD).